

REPORT of SURVEY for REPAIRS, &c.

No. *4640*

No. in Survey held at *Gardiff*

Reg. Book.

Date, first Survey *7th*

(Received at London Office, *15th Aug 1879*)

Last Survey *9th Aug 1879*

1879

Master *Stewart*

YEAR.

MONTH.

1879

8

TONNAGE under Tonnage Deck *1891*

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage *2000*

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm. *1294*

Built at *Newcastle*

When built *1844*

Owners *Fennick & Son*

Port belonging to *Londree*

Residence *London*

By whom built *Palmer's Co.*

Destined Voyage *Mediterranean*

Surveyed Afloat or in Dry Dock *Still in Dry Dock*

Length of Poop *ft.*

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No. *23806*

Port *Iron*

Classed *100 M.*

638

REPAIRS, OR EXAMINATION AS PER RULE

Case of Repairs to be clearly stated.

Placed on Black Sea Dry Dock. Some Butts in Flats of Bottom stopped. Rudder examined, a few timbers in the same renewed. Bottom well coated with Paint & Gallow.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plating (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Vessel appears in good & efficient condition eligible to remain as classed 100 M.

The Amount of Entry Fee ... £ : : received by me, *1479*

Special ... £ : : *11/9 1879*

Certificate (if required)

to be sent as per margin... £ : :

(Travelling Expenses, if any, £)

Committee's Minute

16th September,

18 79.

Character assigned

100 M.

Henry J. Gynell
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

REPORT of SUPPLY for REPAIRS &c. *Verilla*

[Faint, mostly illegible handwritten text in the upper section of the page, possibly describing the nature of the repairs or the state of the vessel.]

Condition of the		Particulars	
Keel	Planks	Planks	Planks
Bottom	Planks	Planks	Planks
Side	Planks	Planks	Planks
Deck	Planks	Planks	Planks
Stowage	Planks	Planks	Planks
Trunk	Planks	Planks	Planks
Hold	Planks	Planks	Planks
Foremast	Planks	Planks	Planks
Mast	Planks	Planks	Planks
Mizzenmast	Planks	Planks	Planks
Yard	Planks	Planks	Planks
Booms	Planks	Planks	Planks
Blocks	Planks	Planks	Planks
Rigging	Planks	Planks	Planks
Canvas	Planks	Planks	Planks
Paint	Planks	Planks	Planks
Provisions	Planks	Planks	Planks
Water	Planks	Planks	Planks
Fire	Planks	Planks	Planks
Tools	Planks	Planks	Planks
Other	Planks	Planks	Planks

[Faint handwritten text at the bottom of the page, likely a signature or summary.]