

# ANNUAL SURVEYS.

No. 3844 Survey held at London Date, first Survey Aug 30 Last Survey Sept 10 1877  
 No. in on the BR Southesk Master Wm Nicoll  
 Reg. Book. 880 Tonnage 1154 Built at Gundee When built 1877-1M  
 By whom built Stephen Owners S Bruce  
 Port belonging to Gundee Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock W & Dry Dock

Last Survey, No. 2046 Port of Iron Classed 100A 3-78.  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom &c coated

*She is now in good condition and entitled to remain as classed*

Committee's Minute 12th September, 1879.  
 Character assigned 100A  
JRM

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 1207 Survey held at London Date, first Survey Aug 16 Last Survey Aug 23 1879  
 No. in on the S Arctura Master Stevens  
 Reg. Book. 1207 Tonnage 1272 Built at Greenock When built 1865-7M  
 By whom built Beck Owners Hamilton Bros  
 Port belonging to Singapore Destined Voyage Wellington  
 If Surveyed Afloat or in Dry Dock Green Dry Dock

Last Survey, No. 20682 Port of Iron Classed 100A 3-78.  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom &c coated

*She is now in good condition and entitled to remain as classed*

Committee's Minute 12th September, 1879.  
 Character assigned 100A  
JRM

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18