

# ANNUAL SURVEYS.

No. 20510 Survey held at London Date, first Survey Sept 20 Last Survey Sept 26 1879  
 No. in on the SS Samuel Laing Master James  
 Reg. Book. 162 Tonnage 479 Built at Newcastle When built 1854  
 By whom built Palmer Owners J. Fenwick & Co  
 Port belonging to London Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Penton Victoria St

Last Survey, No. 22595 Port of London S. I. No. 3-75 Classified 80A1 1-79  
 Present Condition of the Decks good Treenails Pivots good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. brated When put on now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom & coated

*She is now in good condition and eligible to remain as classed*

Committee's Minute 30th September, 1879 Senhouse Martindale  
 Character assigned 80A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) TRW Paid 18

No. 22032 Survey held at London Date, first Survey Sept 28 Last Survey Sept 28 1879  
 No. in on the S Grecian Master Corrance  
 Reg. Book. 655 Tonnage 1272 Built at Greenock When built 1868 10M  
 By whom built Scott Owners Worr  
 Port belonging to Greenock Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 22032 Port of Gron S. I. No. 3-75 Classified 80A1 10-78  
 Present Condition of the Decks good Treenails Pivots good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. brated When put on now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom & coated

*She is now in good condition and eligible to remain as classed.*

Committee's Minute 30th September, 1879 Senhouse Martindale  
 Character assigned 80A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) TRW Paid 18