

22/8/79

ANNUAL SURVEYS.

No. 28498 Survey held at London Date, first Survey Sept 18th Last Survey Sept 15th 1879
 No. in on the SS Agra Master J. Helleour
 Reg. Book. 297 Tonnage 1235 Built at Dumbarton When built 1872 - 10M
 By whom built Senning Owners British India Steam Nav Co.
 Port belonging to Glasgow Destined Voyage Perman full
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St.

Last Survey, No. 22350 Port of Iron Classed 100A 12.78.
 Years assigned. 100A 12.78. Character in Register Book.

| | | | |
|--|-------------|---|-------------|
| Present Condition of the | <u>good</u> | Treenails <u>Pivots</u> | <u>good</u> |
| Decks | | Breasthooks and Stemson | |
| Waterways | " | Transoms, Pointers, and Crutches | " |
| Comings | " | Timbers of the Frame at the Openings | " |
| Upper Deck Beams & Fastenings | " | Ditto ditto at other places | " |
| Lower Deck Beams & Fastenings | " | Keelsons | " |
| Planksheers | " | Clamps and Shelves | " |
| Sheerstrakes | " | Ceiling | " |
| Topsides | " | Rudder | " |
| Wales | " | Copper or Y.M. <u>Coated</u> When put on <u>Now</u> | |
| Plank (Bottom) and Counter | " | Caulking of Bottom, Deck, & Waterways | <u>good</u> |
| Engine Room Skylights | | Coal Bunker, Openings, Lids, &c. | |
| General Observations, Opinion as to Class, &c. | | Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches | |

She is now in good condition and eligible to remain as classed.

Committee's Minute 26th September, 1879.

Character assigned 100A
TBW

Samhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 1357 Survey held at London Date, first Survey Aug 22 Last Survey Sept 4th 1879
 No. in on the SS Assyria Master A. Hay
 Reg. Book. 1357 Tonnage 570 Built at Renfrew When built 1872 - 8M
 By whom built Simons Owners British India Steam Nav Co.
 Port belonging to Glasgow Destined Voyage Perman full
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St.

Last Survey, No. 22098 Port of Iron Classed 100A 10.78
 Years assigned. 100A 10.78 Character in Register Book.

| | | | |
|--|-------------|---|-------------|
| Present Condition of the | <u>good</u> | Treenails <u>Pivots</u> | <u>good</u> |
| Decks | | Breasthooks and Stemson | |
| Waterways | " | Transoms, Pointers, and Crutches | " |
| Comings | " | Timbers of the Frame at the Openings | " |
| Upper Deck Beams & Fastenings | " | Ditto ditto at other places | " |
| Lower Deck Beams & Fastenings | " | Keelsons | " |
| Planksheers | " | Clamps and Shelves | " |
| Sheerstrakes | " | Ceiling | " |
| Topsides | " | Rudder | " |
| Wales | " | Copper or Y.M. <u>Coated</u> When put on <u>Now</u> | |
| Plank (Bottom) and Counter | " | Caulking of Bottom, Deck, & Waterways | <u>good</u> |
| Engine Room Skylights | | Coal Bunkers, Openings, Lids, &c. | |
| General Observations, Opinion as to Class, &c. | | Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches | |

She is now in good condition and eligible to remain as classed.

Committee's Minute 26th September, 1879.

Character assigned 100A
TBW

Samhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18