

ANNUAL SURVEYS.

24602

Rec'd 29/9/78

No. in Reg. Book. **No. 168** Survey held at Gray Date, first Survey August 9 Last Survey Aug 9 1877
 on the Memnonia Master J. M. B. Laro
 Tonnage 1247 Built at Punjab When built 1878
 By whom built Saxford Owners Guthrie & Co. Glasgow
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 21219 Port of Gray
 Present Condition of the
 Decks good Treenails Reich good
 Waterways ok Breasthooks and Stemson ok
 Comings ok Transoms, Pointers, and Crutches ok
 Upper Deck Beams & Fastenings ok Timbers of the Frame at the Openings ok
 Lower Deck Beams & Fastenings ok Ditto ditto at other places ok
 Planksheers ok Keelsons ok
 Sheerstrakes ok Clamps and Shelves ok
 Topsides ok Ceiling ok
 Wales ok Rudder ok
 Plank (Bottom) and Counter ok Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways ok
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

To facilitate the loading and unloading of cargo this vessel has had two additional Port cut in the second stow on each side. @ Port is 2p6. by 2p6. they are strengthened in the same manner as the original Port and are secured with iron 3 x 3 x 1/2 round Rods and 4 x 4 x 1/2 all round Port holes. and in my opinion they do not impair the vessel's strength to any material extent, and she is still much to be depended on for service of class.

Committee's Minute 30th September, 1879.
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) T.B.M. Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



0670-187021