

24/5/79

# ANNUAL SURVEYS.

No. 28501 Survey held at London Date, first Survey Sept 1<sup>st</sup> Last Survey Sept 23<sup>rd</sup> 1879  
 No. in on the SS Merimathachie Master J. Shumack  
 Reg. Book. 979 Tonnage 1245 Built at Glasgow When built 1878 4M  
 By whom built Son J Glas & Co Owners J. J. Jenkins & Co  
 Port belonging to London Destined Voyage China  
 If Surveyed Afloat or in Dry Dock W I Dry Dock

Last Survey, No. 22642 Port of Iron  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom & coated

Classed 100A1 1.79  
 Years assigned. Character in Register Book.

*She is now in good condition and eligible to remain as classed.*

Committee's Minute 23<sup>th</sup> September, 1879.

Character assigned 100A1

Senhouse Martindeale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 256 Survey held at London Date, first Survey Sept 1<sup>st</sup> Last Survey Sept 3<sup>rd</sup> 1879  
 No. in on the S Jeanie Langles Master J. Bolin  
 Reg. Book. 256 Tonnage 1357 Built at St Glasgow When built 1877 6M  
 By whom built Murray Owners S. Law  
 Port belonging to Glasgow Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock W I Dry Dock

Last Survey, No. 21787 Port of Iron  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom Coated &c

Classed 100A1 9.78  
 Years assigned. Character in Register Book.

*She is now in good condition and eligible to remain as classed.*

Committee's Minute 26<sup>th</sup> September, 1879.

Character assigned 100A1

Senhouse Martindeale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18