

24/5/79

24603

ANNUAL SURVEYS.

(Received at London Office, (Rec'd. 25th 9 79))

No. 2850 Survey held at London Date, first Survey Sept 1st Last Survey Sept 23rd 1879
 No. in on the SS Merimathia Master J Starrock
 Reg. Book. 979 Tonnage 1245 Built at Glasgow When built 1878 4M
 By whom built 1807 Son J Glas & Co Owners J J Jenkins & Co
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock W J Dry St

Last Survey, No. 22642 Port of Iron Classed 100A1 1.79
 Years assigned. Character in Register Book.

Present Condition of the		Treenails		Rivets		Decks	
Waterways	Good	Breasthooks and Stemson	Good	Windlass and Capstan	Good	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Condition, how ascertained	From St	Sails	Good
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Anchors, No. of 3 Nos. St J Redge	Good	Cables Part on St	Good
Planksheers	"	Keelsons	"	Hawsers and Warps	"	Standing and Running Rigging	"
Sheerstrakes	"	Clamps and Shelves	"	Cargo and Main Hatchways	Good	Hatches	"
Topsides	"	Ceiling	"	General Observations, Opinion as to Class, &c. <u>Bottom & coated</u>			
Wales	"	Rudder	"	She is now in good condition and eligible to remain as classed.			
Plank (Bottom) and Counter	"	Copper or Y.M. Coated When put on <u>Now</u>	"				
Engine Room Skylights	Good	Caulking of Bottom, Deck, & Waterways	Good				

Committee's Minute 23rd September, 1879.
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping. Seehouse Martindeale
 Certificate (if required) Paid 18

No. 256 Survey held at London Date, first Survey Sept 1st Last Survey Sept 3rd 1879
 No. in on the S Jeanie Sandles Master J Bolin
 Reg. Book. 256 Tonnage 1357 Built at St Glasgow When built 1877 6M
 By whom built Murray Owners J. Law
 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock W J Dry St

Last Survey, No. 21487 Port of Iron Classed 100A1 9.78
 Years assigned. Character in Register Book.

Present Condition of the		Treenails		Rivets		Decks	
Waterways	Good	Breasthooks and Stemson	Good	Windlass and Capstan	Good	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Condition, how ascertained	From St	Sails	Good
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Anchors, No. of 3 Nos. St J Redge	Good	Cables Part on St	Good
Planksheers	"	Keelsons	"	Hawsers and Warps	"	Standing and Running Rigging	"
Sheerstrakes	"	Clamps and Shelves	"	Cargo and Main Hatchways	Good	Hatches	"
Topsides	"	Ceiling	"	General Observations, Opinion as to Class, &c. <u>Bottom Coated &c</u>			
Wales	"	Rudder	"	She is now in good condition and eligible to remain as classed.			
Plank (Bottom) and Counter	"	Copper or Y.M. Coated When put on <u>Now</u>	"				
Engine Room Skylights	Good	Caulking of Bottom, Deck, & Waterways	Good				

Committee's Minute 26th September, 1879.
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping. Seehouse Martindeale
 Certificate (if required) Paid 18

IRON 187-0491