

ANNUAL SURVEYS.

No. 4961 Survey held at Glasgow Date, first Survey 5 Sept Last Survey 8 September 18 79
 No. in on the S.S. "AMARAPOORA" Master Stuart
 Reg. Book. 1619 Tonnage 2464 Built at Glasgow When built 1874 7 mo
 By whom built Scott Owners British & Burmese Steam Navigation Co. Ltd.
 Port belonging to Glasgow Destined Voyage Rangoon
 If Surveyed Afloat or in Dry Dock Govan dry dock

Last Survey, No. 20680 Port of Glasgow Classed S.S. reg. 78 Years assigned. 100 A. 1. Character in Register Book.
 Present Condition of the Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 1874
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained from the deck
 Sails "
 Anchors, No. of "
 Cables "
 Hawser and Warps "
 Standing and Running Rigging Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Is now in good and efficient condition - eligible in my opinion to remain as classed. (Fore main and after masts sealed chipped and painted. part of Coal Bunkers also sealed and painted.)

Committee's Minute 3rd October, 1879. James Dundie
 Character assigned 100 A. 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
B. & M. 8. 9. 79 with limit of 12 months A.S.
 Certificate (if required) Paid 18 79

No. 4961 Survey held at Glasgow Date, first Survey 1st Sept Last Survey 12th Sept 18 79
 No. in on the Iron Ship "Auckland" Master Mr. Dougall
 Reg. Book. 1345 Tonnage 1124 Built at Port Glasgow When built 1874
 By whom built Duncan Owners Albion Shipping Co
 Port belonging to Glasgow Destined Voyage By New Zealand
 If Surveyed Afloat or in Dry Dock Govan dry dock and afloat

Last Survey, No. 21687 Port of Glasgow Classed 100 A. 1 Years assigned. 9. 70 Character in Register Book.
 Present Condition of the Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stemson not seen
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cem When put on 74
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained from the deck
 Sails Said to be complete
 Anchors, No. of 23 1874
 Cables Said to be complete
 Hawser and Warps Good
 Standing and Running Rigging "
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

The bottom scraped and recoated
The is now in good and efficient condition eligible to remain as classed 100 A. 1.

Committee's Minute 3rd October, 1879. W. D. Dundie
 Character assigned 100 A. 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
T.B.W. Certificate (if required) Paid 18 79