

# ANNUAL SURVEYS.

No. 30534 Survey held at London Date, first Survey Sept 28<sup>th</sup> Last Survey Sept 30<sup>th</sup> 1879  
 No. in on the S Roderick Dhu Master R Balver  
 Reg. Book 462 Tonnage 1642 Built at Glasgow When built 1873 12M  
 By whom built Mounsey Owners Williamson Milligan & Co.  
 Port belonging to Liverpool Destined Voyage  
 If Surveyed Afloat or in Dry Dock W I Dry Dock

Last Survey, No. 20452 Port of Liverpool

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Classed	Years assigned.	Character in Register Book.
Waterways	"	Breasthooks and Stemson	"	"	<u>100A-478</u>		
Comings	"	Transoms, Pointers, and Crutches	"	"	<u>88 Lm M-78</u>		
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"			
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"			
Planksheers	"	Keelsons	"	"			
Sheerstrakes	"	Clamps and Shelves	"	"			
Topsides	"	Ceiling	"	"			
Wales	"	Rudder	"	"			
Plank (Bottom) and Counter	"	Copper or Y.M. Coated When put on <u>now</u>					
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>Good</u>				
Coal Bunker, Openings, Lids, &c.		Scuppers	<u>Good</u>				
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>Good</u>				
		Hatches	"				

*She is now in good condition and eligible to remain as classed*

Committee's Minute 7th October, 1879.

Character assigned 100A-478  
TBM

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. Survey held at London Date, first Survey Sept 5<sup>th</sup> Last Survey Sept 5<sup>th</sup> 1879  
 No. in on the SS Sunnibin Castle Master J. Howson  
 Reg. Book 546 Tonnage 1784 Built at Glasgow When built 1875 11M  
 By whom built Napier Owners J. Currie & Co.  
 Port belonging to London Destined Voyage Cape  
 If Surveyed Afloat or in Dry Dock

Last Survey, No. 23542 Port of Liverpool

Present Condition of the					Classed	Years assigned.	Character in Register Book.
Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	<u>100A-578</u>		
Waterways	"	Breasthooks and Stemson	"	"			
Comings	"	Transoms, Pointers, and Crutches	"	"			
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"			
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"			
Planksheers	"	Keelsons	"	"			
Sheerstrakes	"	Clamps and Shelves	"	"			
Topsides	"	Ceiling	"	"			
Wales	"	Rudder	"	"			
Plank (Bottom) and Counter	"	Copper or Y.M. Coated When put on <u>now</u>					
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>Good</u>				
Coal Bunkers, Openings, Lids, &c.		Scuppers	<u>Good</u>				
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>Good</u>				
		Hatches	"				

*She is now in good condition and eligible to remain as classed. The officer in charge were informed that SS M/V was nearly done.*

Committee's Minute 7th October, 1879.

Character assigned 100A-578  
TBM

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18