

Damage Repair
REPORT of SURVEY for REPAIRS, &c.

No. 2853

No. in
Reg. Book.

Survey held at

London

Date, first Survey

Sept 24

Last Survey

Oct 22

1879

288 on the

SS Orwell

Master

J. Goodie

TONNAGE under Tonnage Deck

614

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

632

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm.

404

Built at

Newcastle

When built

1864

7

Owners

J. Fenwick & Co

Port belonging to

London

Residence

By whom built

Palmer

Destined Voyage

Courtesy

If Surveyed Afloat or in Dry Dock

Victoria Dock Afloat

Length of Poop

4

ft.

Ditto, Forecastle

4

ft.

Ditto, Raised Quarter Deck

15

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

24201

Port

Iron

Classed

A1

7.73

I.S. No. 3-7488

See

12-77

REPAIRS, OR EXAMINATION AS PER RULE

At the present time owing to

Damage.

Portside Renewed 4 Bow plates next the Stern below the Sheerstrake.

Starboardside 4 Bow plates next the Stern taken off heated and made fair & replaced, 4 broken frames compensated with additional Angle Iron.

Main Stern heated and made fair.

Present Condition of the

Decks	good	Treenails	Revised	good	Windlass and Capstan	good
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	From St
Planksheers	"	Keelsons	"	"	Sails	good
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of & Bcs.	St & Reddy
Topsides	"	Ceiling	"	"	Cables	Part on St
Wales	"	Rudder	"	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	When put on	"	Standing & Running Rigginy	"
Engine Room Skylights	good	Caulking of				
Coal Bunker, Openings, Lids, &c.	good	Bottom, Deck, & Waterways	good			
Scuppers	good					
Cargo and Main Hatchways	good					
Hatches	good					

General Observations, Opinion as to Class, &c.

Coated above light line forward

She is now in good condition and eligible to remain as classed

Survey Fee £ 2-2-0

The Amount of Entry Fee ...

received by me,

9 Oct 1879

Special ...

Certificate (if required) ...

Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £)

Committee's Minute

10th October, 1879.

Character assigned

As
TBW



© 2019

Lloyd's Register Foundation

IRON 488-0077