

# ANNUAL SURVEYS.

(Rec'd. 18th 10/79)

No. in Reg. Book. No. 38589 Survey held at London Date, first Survey Oct 1878 Last Survey Oct 17<sup>th</sup> 1879  
 on the SS Seine Master Manning  
 Tonnage 2200 Built at London When built 1863  
 By whom built Thames Ship Co Owners Jel Sen & Mainz Co  
 Port belonging to London Destined Voyage Singapore &c  
 If Surveyed Afloat or in Dry Dock Thames Iron Works by Sh

Last Survey, No. 23095 Port of Iron

Present Condition of the

Decks	Treenails	Parab	Iron	Years assigned.	Character in Register Book
Waterways	4	Breasthooks and Stenson	4	Classed	100 A - 2.75
Comings	4	Transoms, Pointers, and Crutches	4	I.S. cl. 3-75	SS Iron Wk. 77
Upper Deck Beams & Fastenings	4	Timbers of the Frame at the Openings	4		
Lower Deck Beams & Fastenings	4	Ditto ditto at other places	4		
Planksheers	4	Keelsons	4		
Sheerstrakes	4	Clamps and Shelves	4		
Topsides	4	Ceiling	4		
Wales	4	Rudder	4		
Plank (Bottom) and Counter	4	Copper or Y.M. Coated When put on	4		
Engine Room Skylights	4	Caulking of Bottom, Deck, & Waterways	4		
Coal Bunker, Openings, Lids, &c.	4	Scuppers	4		
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	4		

*She is now in good condition and eligible to remain as classed*

*Senhouse Martindale*

Committee's Minute 21st October, 1879.

Character assigned 100 *TRW* Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18

No. 157 Survey held at London Date, first Survey Oct 6 Last Survey Oct 16<sup>th</sup> 1879  
 on the SS Chyebassa Master Stowell  
 Tonnage 1714 Built at Sturminster When built 1874 - 7M  
 By whom built Senning Owners W Mackinnin  
 Port belonging to Glasgow Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Sh

Last Survey, No. 22727 Port of Iron

Present Condition of the

Decks	Treenails	Parab	Iron	Years assigned.	Character in Register Book
Waterways	4	Breasthooks and Stenson	4	Classed	100 A 1.75
Comings	4	Transoms, Pointers, and Crutches	4	SS Iron Wk 78	
Upper Deck Beams & Fastenings	4	Timbers of the Frame at the Openings	4		
Lower Deck Beams & Fastenings	4	Ditto ditto at other places	4		
Planksheers	4	Keelsons	4		
Sheerstrakes	4	Clamps and Shelves	4		
Topsides	4	Ceiling	4		
Wales	4	Rudder	4		
Plank (Bottom) and Counter	4	Copper or Y.M. Coated When put on	4		
Engine Room Skylights	4	Caulking of Bottom, Deck, & Waterways	4		
Coal Bunkers, Openings, Lids, &c.	4	Scuppers	4		
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	4		

*She is now in good condition and eligible to remain as classed*

*Senhouse Martindale*

Committee's Minute 21st October, 1879.

Character assigned 100 *TRW* Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18