

# REPORT of SURVEY for REPAIRS, &c.

No. 4496

No. in  
Reg. Book.

Survey held at

Date, first Survey

Last Survey

1849

on the

Master

YEAR.

MONTH.

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, out on Beam

Engine Room

Reg. Tons as St' mer, out on Bm.

Built at

When built

Owners

Port belonging to

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

Port

Classed

REPAIRS, OR EXAMINATION AS PER RULE

Lead on blocks in dry dock, and the hull & bottom examined; repairs made, and the holds cleared. All the close caulking in the holds removed; also, the Coal Bunkers cleared, and while thus exposed the whole of the Bone Work examined, and the plating & shells drilled in places on each side. The Cementing of Bottom Carefully examined, and the Bone Work freed of oxidation. The plank-sheers, waterways, deck & examined. — The Chain Cables and Anchors renewed, and the general equipment attended to.

Repairs now done. The upper Ripe plate doubled on each side to about 50' with 8 plates, said plating being found damaged & bent. The hull, stem, and stem-post repaired, and a large number of rivets.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Plank-sheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

The Amount of Entry Fee

Special

Certificate (if required)

Travelling Expenses, if any, &

Committee's Minute

Character assigned

21st October,

1872.

A 4 c P

S.S. No 3. 79

JTBW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Lloyd's Register Foundation

IRON 488-0153



