

ANNUAL SURVEYS.

(Received at London Office, (Rec'd. 16th. 10. 79.)

No. 38581 Survey held at London Date, first Survey Oct 8 Last Survey Oct 14 1879
 No. in on the 5 Wherronese Master J Chapman
 Reg. Book. 233 Tonnage 1711 Built at Belfast When built 1855
 By whom built London Owners G Duncan
 Port belonging to London Destined Voyage Caruiff & Bombay
 If Surveyed Afloat or in Dry Dock Penton Victoria Dock

Last Survey, No. 22220 Port of Ton
 Present Condition of the
 Decks good Treennails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on new
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. Bottom & Coated

Classed 100 A1 1178
 SS Lon M178
 P.P. No. 3-74

Windlass and Capstan good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained From Stk
 Sails good
 Anchors, No. of 3 Buo. St & Redys
 Cables Part on Stk good
 Hawesers and Warps "
 Standing and Running Rigging "

Committee's Minute 21st October, 1879.

Character assigned 100 A1 T.B.W.

Senhouse Martin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) " Paid " 18 "

No. 293 Survey held at London Date, first Survey Sept 24 Last Survey Oct 11 1879
 No. in on the 5 Margaret Galbraith Master J Ferguson
 Reg. Book. 293 Tonnage 84 Built at Glasgow When built 1868
 By whom built Duncan Owners Shaw Sarril & Co
 Port belonging to Glasgow Destined Voyage Obago
 If Surveyed Afloat or in Dry Dock Greens Dock

Last Survey, No. 19507 Port of Ton
 Present Condition of the
 Decks good Treennails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on new
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. Bottom & Coated

Classed 100 A1 1077
 SS Lon M2-77

Windlass and Capstan good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained From Stk
 Sails good
 Anchors, No. of 3 Buo. St & Redys
 Cables Part on Stk good
 Hawesers and Warps "
 Standing and Running Rigging "

Committee's Minute 21st October, 1879.

Character assigned 100 A1 T.B.W.

Senhouse Martin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) " Paid " 18 "