

ANNUAL SURVEYS.

(Received at London Office, (Rec'd 14th 10 79))

No. 4244 Survey held at Dundee Date, first Survey Sept: 22nd Last Survey Sept: 24th 1879
 No. in Reg. Book. 17 on the I.S.S. "Queen" Master Sangster
 Tonnage 148 Built at Glasgow When built 1854
 By whom built W.B. Thompson Owners W.B. Thompson
 Port belonging to Dundee Destined Voyage London
 If Surveyed Afloat or in Dry Dock On Patent Slip and Afloat with dunnage in main hold.

Last Survey, No. 2294 Port of Iron Classed 100A-1

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	St. Dun No 3-76
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	10.78
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Windlass and Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Boats <u>"</u>
sheers <u>"</u>	Keelsons <u>Where exposed Good</u>	Masts, Yards, &c. <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shells <u>Stringers</u> <u>"</u>	Condition, how ascertained <u>Beam from deck</u>
Upsides <u>"</u>	Ceiling <u>Where exposed</u> <u>"</u>	Sails <u>Good</u>
Wales <u>"</u>	Rudder <u>Good and efficient</u>	Anchors, No. of <u>2 B. 18. 1 K.</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Cement</u> When put on <u>"</u>	Cables <u>"</u>
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Hawsers and Warps <u>"</u>
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>"</u>	Standing and Running Rigging <u>"</u>
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways <u>Good</u>	Hatches <u>"</u>

Vessel placed on blocks, keel bottom & sides cleaned down and examined; recoated bottom and sides.
 This vessel is now in good and efficient condition and eligible in my opinion to remain as Classed.

Committee's Minute 17th October, 1879
 Character assigned 100
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

Present Condition of the Decks <u> </u>	Treenails <u> </u>	Windlass and Capstan <u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	Masts, Yards, &c. <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	Condition, how ascertained <u> </u>
Plank sheers <u> </u>	Keelsons <u> </u>	Sails <u> </u>
Sheerstrakes <u> </u>	Clamps and Shells <u> </u>	Anchors, No. of <u> </u>
Topsides <u> </u>	Ceiling <u> </u>	Cables <u> </u>
Wales <u> </u>	Rudder <u> </u>	Hawsers and Warps <u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	Standing and Running Rigging <u> </u>
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u> </u>	Cargo and Main Hatchways <u> </u>
Coal Bunkers, Openings, Lids, &c. <u> </u>	Scuppers <u> </u>	Hatches <u> </u>
General Observations, Opinion as to Class, &c.		

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18