

ANNUAL SURVEYS.

24460

No. 38588 Survey held at London Date, first Survey Oct 13 Last Survey Oct 13 1879
 No. in on the SS William Purkitt Master Frieman
 Reg. Book. 318 Tonnage 1232 Built at Newcastle When built 1878 - 11M
 By whom built Leslie Owners Sarup Surtees & Co
 Port belonging to London Destined Voyage Colombo
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 22663 Port of Iran

Classed 100 A 1.75

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M. Coated~~ When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom to be coated.

She is now in good condition and eligible to remain as classed

Committee's Minute 21st October, 1879.

Character assigned 100 A 1.75 TRW

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at London Date, first Survey Sept 15 Last Survey Sept 15 1879
 No. in on the SS Beaconsfield Master "
 Reg. Book. 146 Tonnage 1118 Built at Newcastle When built 1877 - 7M
 By whom built Syne & Co Owners G. Blough
 Port belonging to North Shields Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 23247 Port of Iran

Classed 100 A 4.75

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M. Coated~~ When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom to be coated.

She is now in good condition and eligible to remain as classed.

Committee's Minute 21st October, 1879.

Character assigned 100 A 4.75 TRW

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18