

ANNUAL SURVEYS.

No. 584. Survey held at Antwerp Date 13-15th Octob 1879.
 on the Cham. Barque "Deanfield" Master Genies
 Tonnage 1072 Built at Port Glasgow When built 1878 - 4 man
 By whom built Russel Owners R. B. Marnaghton
 Port belonging to Liverpool Destined Voyage Antw. - Shanghai
 If Surveyed Afloat or in Dry Dock in dry dock

Last Survey, No. 20808 Port of Antw Classed 100 A.S.
5-78

The present Condition of the

| | | |
|--|---|---|
| Decks <u>good</u> | Treenails <u>Pinets</u> <u>good</u> | Windlass and Capstan <u>good</u> |
| Waterways <u>"</u> | Breasthooks and Stemson <u>"</u> | Pumps <u>"</u> |
| Comings <u>"</u> | Transoms, Pointers, and Crutches <u>"</u> | Boats <u>"</u> |
| Upper Deck Beams & Fastenings <u>"</u> | Timbers of the Frame at the Openings <u>"</u> | Masts, Yards, &c. <u>"</u> |
| Lower Deck Beams & Fastenings <u>"</u> | Ditto ditto at other places <u>"</u> | Sails <u>"</u> |
| Planksheers <u>"</u> | Keelsons <u>"</u> | Anchors No. of <u>6</u> |
| Sheerstrakes <u>"</u> | Clamps and Shelves <u>"</u> | Cables <u>suffic in size & length</u> |
| Topsides <u>"</u> | Ceiling <u>"</u> | Hawsers and Warps <u>good</u> |
| Wales <u>"</u> | Rudder <u>"</u> | Standing & Running Rigging <u>"</u> |
| Plank (Bottom) and Counter <u>"</u> | Copper <u>Pinet</u> When put on <u>1871</u> | |

General Observations and Opinion,
Placed in dry dock and examined all outside & inside as far as practicable and found all ahead seem in good condition, with the exception that many of the rivet heads at the height of the light water line were found more or less rounded but of no danger just now. Several defective rivets in rudder were taken out and replaced by new. This vessel is in my opinion in a satisfactory condition of class.

Committee's Minute 17th Octob 18 79
 Character assigned 100 A.S.
For retained L. 2. 2. 0.
Certificate 5 Certificate (if required) yes

No. _____ Survey held at _____ Date _____ 18 ____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

| | | |
|-------------------------------------|--|----------------------------------|
| Decks _____ | Treenails _____ | Windlass and Capstan _____ |
| Waterways _____ | Breasthooks and Stemson _____ | Pumps _____ |
| Comings _____ | Transoms, Pointers, and Crutches _____ | Boats _____ |
| Upper Deck Beams & Fastenings _____ | Timbers of the Frame at the Openings _____ | Masts, Yards, &c. _____ |
| Lower Deck Beams & Fastenings _____ | Ditto ditto at other places _____ | Sails _____ |
| Planksheers _____ | Keelsons _____ | Anchors No. of _____ |
| Sheerstrakes _____ | Clamps and Shelves _____ | Cables _____ |
| Topsides _____ | Ceiling _____ | Hawsers and Warps _____ |
| Wales _____ | Rudder _____ | Standing & Running Rigging _____ |
| Plank (Bottom) and Counter _____ | Copper _____ When put on _____ | |

General Observations and Opinion, _____
 Caulking of Bottom, Deck, and Waterways _____
 Committee's Minute _____ 18 ____
 Character assigned _____
 Certificate (if required). _____