

ANNUAL SURVEYS.

24448
(Rec'd. 18th 10 79)

No. in Reg. Book. **No. 38590** Survey held at London Date, first Survey Oct 14 Last Survey Oct 14 18 79
 on the SS Taymouth Castle Master _____
 Tonnage 1172 Built at Glasgow When built 1877 S.M.
 By whom built Barclay Owners J Currie & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Thames Iron Works by SA

Last Survey, No. 24201 Port of Iron

Classed 100 A-1-5.79

Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Opsides " Ceiling "
 Sides " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Iron
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated

She is now in good condition and eligible to remain as classed.

Senhouse Martin

Committee's Minute 21st October, 18 79.

Character assigned 100 A-1 DBW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 36 Survey held at London Date, first Survey Oct 14 Last Survey Oct 16 18 79
 on the BN Earl Granville Master J Campbell
 Tonnage 556 Built at Port Glasgow When built 1877 S.M.
 By whom built London Owners A McAlister
 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Blackburne & Co by SA

Last Survey, No. 20945 Port of Iron

Classed 100 A-1-5.78

Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Opsides " Ceiling "
 Sides " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Iron
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated

She is now in good condition and eligible to remain as classed.

Senhouse Martin

Committee's Minute 21st October, 18 79.

Character assigned 100 A-1 DBW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

Japan in Castle
Earl Granville



© 2019
Lloyd's Register
Foundation