

ANNUAL SURVEYS.

No. 4971 Survey held at Glasgow Date, first Survey 31st Sept Last Survey 14th October 1879
 No. in on the Iron Ship "Marlborough" Master Anderson
 Reg. Book. 1124 Tonnage 1121 Built at Glasgow When built 1876
 By whom built Duncan Owners J Colbraigh
 Port belonging to Glasgow Destined Voyage Cy. New Zealand
 If Surveyed Afloat or in Dry Dock Govan dry dock

Last Survey, No. 21801 Port of Govan

Present Condition of the
Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Classed

Years assigned.

Character in Register Book.

100AS

9.20

Treenails Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper or Y.M. Cement When put on 76

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained from the decks

Sails Said to be complete

Anchors, No. of 318-18 2K

Cables Said to be complete

Hawsers and Warps

Standing and Running Rigging

The bottom scraped and recoated - She is in good and efficient condition eligible to remain as classed 100AS

Committee's Minute

17th October,

1879

Character assigned

100AS

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. 4971 Survey held at Glasgow Date, first Survey and Last Survey 10th October 1879
 No. in on the Iron Ship "Rokeby" Master Kidd
 Reg. Book. 734 Tonnage 734 Built at Hartlepool When built 1874
 By whom built Withy Owners G Peppan & Co
 Port belonging to W Hartlepool Destined Voyage Cy Odessa
 If Surveyed Afloat or in Dry Dock Govan dry dock

Last Survey, No. 245745 Port of Govan

Present Condition of the
Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Classed

Years assigned.

Character in Register Book.

90AS

83 Hpt Nov 79

8.79

Treenails Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper or Y.M. Cem When put on 74

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained from the decks

Sails Said to be complete

Anchors, No. of 318 18 2K

Cables Said to be complete

Hawsers and Warps

Standing and Running Rigging

The bottom scraped and recoated She is in good and efficient condition eligible to remain as classed 90AS

Committee's Minute

17th October,

1879

Character assigned

90AS

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18