

ANNUAL SURVEYS.

(Rec'd, 14th 10/79)

No. in Reg. Book. **No. 2856** Survey held at **London** Date, first Survey **4 October** Last Survey **4 October** 18**79**
 on the **"Lionel Wyn"** Master **Thos Lewis**
 Tonnage **1665** Built at **Port Glasgow** When built **1877** 2 m
 By whom built **Russell** Owners **H. Pritchard**
 Port belonging to **Glasgow** Destined Voyage **Sydney**
 If Surveyed Afloat or in Dry Dock **Princes dry dock**

Last Survey, No. **14908** Port of **Iron** Classed **100 A1**
 Present Condition of the **Good** Years assigned **2.77** Character in Register Book

Waterways de	Treenails de	Breasthooks and Stemson de	Windlass and Capstan Good
Outriggers de	Transoms, Pointers, and Crutches de	Timbers of the Frame at the Openings de	Pumps Two de
Upper Deck Beams & Fastenings de	Ditto ditto at other places de	Keelsons de	Boats four de
Lower Deck Beams & Fastenings de	Clamps and Shelves de	Ceiling de	Masts, Yards, &c. de
Planksheers de	Rudder de	Copper or Y.M. ✓ When put on ✓	Condition, how ascertained from deck
Sheerstrakes de	Caulking of Bottom, Deck, & Waterways de	Scuppers de	Sails well found
Topsides de	Engine Room Skylights de	Coal Bunker, Openings, Lids, &c. de	Anchors, No. of 3 B. 1 P. & Hedges
Wales de	General Observations, Opinion as to class, &c. This vessel appears in good condition and eligible to remain as classed. Bottom recoated. Surveyed with port outward cargo in the midship hold.	Cargo and Main Hatchways de	Cables complete
Plank (Bottom) and Counter de		Hatches de	Hawsers and Warps sufficient
			Standing and Running Rigging good

Committee's Minute

17th October,

18 79.

Character assigned

100 A1

T.B.W.

Thos. Longdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. in Reg. Book. **No. 213** Survey held at **London** Date, first Survey **8 October** Last Survey **11 October** 18**79**
 on the **"West York"** Master **W. Hambley**
 Tonnage **689** Built at **Sunderland** When built **1846** 2
 By whom built **dexford** Owners **Thompson**
 Port belonging to **Lpool** Destined Voyage **Brisbane**
 If Surveyed Afloat or in Dry Dock **Ratcliffe dry dock**

Last Survey, No. **21443** Port of **Iron** Classed **100 A1**
 Present Condition of the **Good** Years assigned **7.78** Character in Register Book

Decks Good	Treenails de	Breasthooks and Stemson de	Windlass and Capstan Good
Waterways de	Transoms, Pointers, and Crutches de	Timbers of the Frame at the Openings de	Pumps two de
Outriggers de	Ditto ditto at other places de	Keelsons de	Boats four de
Upper Deck Beams & Fastenings de	Clamps and Shelves de	Ceiling de	Masts, Yards, &c. de
Lower Deck Beams & Fastenings de	Rudder de	Copper or Y.M. ✓ When put on ✓	Condition, how ascertained from deck
Planksheers de	Caulking of Bottom, Deck, & Waterways de	Scuppers de	Sails well found
Sheerstrakes de	Engine Room Skylights de	Coal Bunkers, Openings, Lids, &c. de	Anchors, No. of 3 B. 1 P. & Hedges
Topsides de	General Observations, Opinion as to Class, &c. This vessel appears in good condition and eligible to remain as classed. Bottom recoated. Surveyed with ballast over the hold.	Cargo and Main Hatchways de	Cables complete
Wales de		Hatches de	Hawsers and Warps sufficient
Plank (Bottom) and Counter de			Standing and Running Rigging good

Committee's Minute

17th October,

18 79.

Character assigned

100 A1

T.B.W.

Thos. Longdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

Leirid Wyr

West Ymr



© 2019

Lloyd's Register
Foundation