

ANNUAL SURVEYS.

24828

No. 38599 Survey held at London Date, first Survey 4 Oct 79 Last Survey 22 October 1879
No. in on the Bⁿ Glance Master L. Bas
Reg. Book. 374 Tonnage 587 1/2 Built at Sunderland When built 1869 10mo
By whom built Watson Owners W. Feller
Port belonging to London Destined Voyage Singapore
If Surveyed Afloat or in Dry Dock Fletcher's Dry Dock

Last Survey, No. 22114 Port of London

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	S.S. Due to 2. 78	10. 78
Waterways	<u>Do</u>	Breasthooks and Stemson		<u>Do</u>	Windlass and Capstan	<u>Good</u>
Comings	<u>Do</u>	Transoms, Pointers, and Crutches		<u>Do</u>	Pumps	<u>Do</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame at the Openings		<u>Do</u>	Boats	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Ditto ditto at other places		<u>Do</u>	Masts, Yards, &c.	<u>Do</u>
Planksheers	<u>Do</u>	Keelsons		<u>Do</u>	Condition, how ascertained	<u>From deck</u>
Sheerstrakes	<u>Do</u>	Clamps and Shelves		<u>Do</u>	Sails	<u>Good</u>
Topsides	<u>Do</u>	Ceiling		<u>Do</u>	Anchors, No. of	<u>3B . 1S . 2K</u>
Wales	<u>Do</u>	Rudder		<u>Do</u>	Cables	<u>part seen</u> <u>Good</u>
Plating (Bottom) and Counter	<u>Do</u>	Copper or V.M. Cement When put on	<u>1869</u>		Hawsers and Warps	<u>Do</u>
		Caulking of			Standing and Running Rigging	<u>Do</u>
		Bottom, Deck, & Waterways	<u>Good</u>			

Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Do Cargo and Main Hatchways Do Hatches Do

General Observations, Opinion as to Class, &c. Vessel placed in dry dock and her bottom scraped and painted. Seen with ballast lying in hold.
She is now in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 24th October, 1879.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. Survey held at London Date, first Survey 10 Oct 79 Last Survey 22 Oct 1879

No. in on the Bⁿ British Empire Master Rowe
Reg. Book. 760 Tonnage 484 1/2 Built at Hartlepool When built 1868 2mo
By whom built Denton Owners R. Brewis
Port belonging to Hartlepool Destined Voyage Rangoon
If Surveyed Afloat or in Dry Dock Carters Dry Dock

Last Survey, No. 21832 Port of London

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	S.S. Due to 2. 78	10. 78
Waterways	<u>Do</u>	Breasthooks and Stemson		<u>Do</u>	Windlass and Capstan	<u>Good</u>
Comings	<u>Do</u>	Transoms, Pointers, and Crutches		<u>Do</u>	Pumps	<u>Do</u>
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame at the Openings		<u>Do</u>	Boats	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Ditto ditto at other places		<u>Do</u>	Masts, Yards, &c.	<u>Do</u>
Planksheers	<u>Do</u>	Keelsons		<u>Do</u>	Condition, how ascertained	<u>From deck</u>
Sheerstrakes	<u>Do</u>	Clamps and Shelves		<u>Do</u>	Sails	<u>Good</u>
Topsides	<u>Do</u>	Ceiling		<u>Do</u>	Anchors, No. of	<u>3B . 1S . 2K</u>
Wales	<u>Do</u>	Rudder		<u>Do</u>	Cables	<u>part seen</u> <u>Good</u>
Plating (Bottom) and Counter	<u>Do</u>	Copper or V.M. Cement When put on	<u>68</u>		Hawsers and Warps	<u>Do</u>
		Caulking of			Standing and Running Rigging	<u>Do</u>
		Bottom, Deck, & Waterways	<u>Good</u>			

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Do Cargo and Main Hatchways Do Hatches Do

General Observations, Opinion as to Class, &c. Vessel placed in dry dock and her bottom scraped and painted. Seen with ballast lying in hold.
She is now in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 24th October, 1879.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18