

# ANNUAL SURVEYS.

(Revised 25th 10/79)

No. in Reg. Book. 468 No. 78615 Survey held at London Date, first Survey 1 October Last Survey 10 October 1879  
 on the BC Walseley Master Park  
 Tonnage 340 Built at Greenwich When built 1876 7th  
 By whom built J. Scott Owners Pullard, King & Co  
 Port belonging to London Destined Voyage Natal  
 If Surveyed Afloat or in Dry Dock

Last Survey, No. 21984 Port of Iron

Present Condition of the Decks	<u>Good</u>	Freemasts	<u>Good</u>	Years assigned.	<u>100 A1</u>	Character in Register Book.	<u>10.78</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Classed			
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>				
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	Windlass and Capstan	<u>Good</u>		
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>	Pumps	<u>two</u>	<u>do</u>	
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Boats	<u>three</u>	<u>do</u>	
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	Masts, Yards, &c.	<u>do</u>	<u>do</u>	
Topsides	<u>do</u>	Ceiling	<u>do</u>	Condition, how ascertained	<u>from deck</u>		
Wales	<u>do</u>	Rudder	<u>do</u>	Sails	<u>well found</u>		
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M.	<u>✓</u>	Anchors, No. of	<u>3 B. 1 P. &amp; Redges</u>		
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>	Cables	<u>complete</u>		
General Observations, Opinion as to Class, &c.		When put on	<u>✓</u>	Hawsers and Warps	<u>Sufficient</u>		
		Scuppers	<u>Good</u>	Standing and Running Rigging	<u>Good</u>		
				Cargo and Main Hatchways	<u>Good</u>		
				Hatches	<u>Good</u>		

Bottom cleaned and recoated. This vessel appears in good condition and eligible to remain as classed.

Committee's Minute 31st October, 1879.

Character assigned 100 A1

TBW

J. W. Douglass  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. 1137 No. 20815 Survey held at London Date, first Survey 22 Oct. Last Survey 23 Oct. 1879  
 on the BC "Stracathro" Master J. G. Millar  
 Tonnage 459 115 1080 Built at Dundee When built 1876 8th mo.  
 By whom built Gourlay Owners D. Bruce & Co.  
 Port belonging to Dundee Destined Voyage Auckland  
 If Surveyed Afloat or in Dry Dock West India Graving Dock.

Last Survey, No. 20815 Port of Iron

Present Condition of the Decks	<u>Good</u>	Freemasts	<u>Good</u>	Years assigned.	<u>100 A1</u>	Character in Register Book.	<u>10.78</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Classed			
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>				
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	Windlass and Capstan	<u>do</u>		
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>	Pumps	<u>do</u>		
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Boats	<u>6 in number</u>		
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	Masts, Yards, &c.	<u>do</u>		
Topsides	<u>do</u>	Ceiling	<u>do</u>	Condition, how ascertained	<u>from deck &amp; engine</u>		
Wales	<u>do</u>	Rudder	<u>do</u>	Sails	<u>do</u>		
Plank (Bottom) and Counter	<u>do</u>	Copper or F.M.	<u>Paint</u>	Anchors, No. of	<u>3 B. 1 St. 2 H</u>	<u>do</u>	
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>good</u>	Cables	<u>part seen</u>	<u>do</u>	
General Observations, Opinion as to Class, &c.		When put on	<u>now</u>	Hawsers and Warps	<u>do</u>		
		Scuppers	<u>do</u>	Standing and Running Rigging	<u>do</u>		
				Cargo and Main Hatchways	<u>good</u>		
				Hatches	<u>do</u>		

Bottom cleaned & repainted.

Surveyed with ballast in hold, in way of main hatch.

This vessel is in good condition & eligible, in my opinion, to remain as classed.

Committee's Minute 31st October, 1879.

Character assigned 100 A1

TBW

W. Faulstich  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18