

REPORT of SURVEY for REPAIRS, &c.

No. *4677* Survey held at *Cardiff* Date, first Survey *21st* Last Survey *22nd Mtr 1874*
 Reg. Book. *325* on the Ship *"Dolbadern Castle"* Master *Williams*
 Tonnage under Tonnage Deck *898* Built at *Sunderland* When built *1863. 11.*
 Ditto of Spar Deck, or Awning Deck Owners *Hughes & Co* Port belonging to *Liverpool*
 Ditto of Poop Ditto of Raised Qr. Dk. Residence *Menai Bridge.*
 Ditto of Houses on Deck By whom built *Bernald.* Destined Voyage *Singapore*
 Gross Tonnage *989* ☒ Surveyed Afloat ☐ in Dry Dock *Roath Dry Dock*
 Crew Space, as per Rule *989*
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm.
 Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.*
 Last Survey, No. *X 19836* Port *Iron*
 Classed *S.S. No. 3. 1/6* 12.3

REPAIRS, OR EXAMINATION AS PER RULE

Placed on blocks in Dry Dock. Bottom well cleaned & coated with Paint. Rudder working, new Steel pintle fitted, other pintles and braces bushed & readjusted

Present Condition of the	<i>Good</i>	Treenails <i>Where seen</i>	<i>Good</i>	Windlass and Capstan	<i>Good</i>
Decks	<i>"</i>	Breasthooks and Stemson	<i>"</i>	Pumps	<i>"</i>
Waterways	<i>"</i>	Transoms, Pointers, and Crutches	<i>"</i>	Boats	<i>"</i>
Comings	<i>"</i>	Timbers of the Frame at the openings	<i>"</i>	Masts, Yards, &c.	<i>"</i>
Upper Deck Beams & Fastenings	<i>"</i>	Ditto Ditto at other places	<i>"</i>	Condition, how ascertained	<i>fr. Dec & Eng.</i>
Lower Deck Beams & Fastenings	<i>"</i>	Keelsons	<i>"</i>	Sails	<i>Super</i>
Planksheers	<i>"</i>	Clamps and Shelves <i>Stringers &c</i>	<i>"</i>	Anchors No. of	<i>as seen</i>
Sheerstrakes	<i>"</i>	Ceiling	<i>"</i>	Cables	<i>Good</i>
Topsides <i>Plating</i>	<i>"</i>	Rudder	<i>"</i>	Hawsers and Warps	<i>Good</i>
Wales	<i>"</i>	Copper <i>Paint</i> When put on <i>now</i>	<i>"</i>	Standing & Running Rigging	<i>Eff't</i>
Plank (Bottom) and Counter	<i>"</i>	Caulking of	<i>"</i>	Cargo and Main Hatchways	<i>Good</i>
Engine Room Skylights	<i>"</i>	Bottom, Deck, & Waterways	<i>Good</i>	Hatches	<i>Good</i>
Coal Bunker, Openings, Lids, &c.	<i>"</i>	Scuppers	<i>"</i>		

General Observations, Opinion as to Class, &c.

Vessel appears in good & efficient condition, eligible to remain as classed

The Amount of Entry Fee ... £ : : received by me, *29/10 1874*
 Special ... £ : :
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)

Committee's Minute *4th November, 1874*


Character assigned *DBU*

Henry J. Spruell
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019
 Lloyd's Register
 Foundation

¹
(Dolbadern Castle.)
²



© 2019

Lloyd's Register
Foundation