

REPORT of SURVEY for REPAIRS, &c.

No. 38617

(Rec'd. 1st 11 79)

No. in Reg. Book. Survey held at London Date, first Survey 29th Oct 78 Last Survey 29th Oct 78 1879
 on the V. S. "Mona" (late "Agmar") Master Bromley
 TONNAGE under Tonnage Deck 435
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 555
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. 425
 Built at Hull When built 1866
 Owners Wm Bailey Port belonging to Hull
 Residence
 By whom built Carle Destined Voyage Ghent
 If Surveyed Afloat or in Dry Dock Fountain Dry Dock Ways

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
 Last Survey, No. 24914 Port Good Classed A.1.
S.S. Lonsdale 78
S.S. No 3-75

REPAIRS, OR EXAMINATION AS PER RULE

Bottom examined Rudder unhung and rehushed, Part bunker cleared, and the stoke hole plates lifted for examination of the damaged plate, found the Cement broken and part gone in way of the damage, the plate being only indented and not cracked, the Cement where broken renewed.

Present Condition of the				
Decks	<u>Good</u>	Trunnels	<u>Keels</u>	<u>Good</u>
Waterways	<u>Good</u>	Breasthooks and Stemson	<u>Good</u>	Windlass and Capstan
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	<u>Good</u>	Pumps
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the openings	<u>Good</u>	Boats
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto Ditto at other places	<u>Good</u>	Masts, Yards, &c.
Planksheers	<u>Good</u>	Keelsons	<u>Good</u>	Condition, how ascertained
Sheerstrakes	<u>Good</u>	Clamps and Shelves	<u>Good</u>	Sails
Topsides	<u>Good</u>	Ceiling	<u>Good</u>	Anchors No. of
Wales	<u>Good</u>	Rudder	<u>Good</u>	Cables
Plank (Bottom) and Counter	<u>Good</u>	Copper	<u>Good</u>	Hawsers and Warps
		Caulking of	<u>Good</u>	Standing & Running Rigging
		Bottom, Deck, & Waterways	<u>Good</u>	

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. The repairs and examination of the bottom, recommended in the Report attached, having been complied with, she is in my opinion eligible to remain as classed.

The Amount of Entry Fee ... £ : : received by me, 11/11/79 Special ... £ : : 3/11/79
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)

Committee's Minute 4th November 18 79

Character assigned A.1.

Surveyor to Lloyd's Register of British and Foreign Shipping.