

ANNUAL SURVEYS.

No. 587 Survey held at Antwerp Date 9-25th October 1879
 on the Ship S.S. "Mio. Peio" Master A. L. G. G. G.
 Tonnage 471 Built at Newcastle When built 1865-9 mo.
 By whom built Bombardier Owners Compagnie Belge
 Port belonging to Brussels Destined Voyage Antwerp - Havre
 If Surveyed Afloat or in Dry Dock in dry dock & afloat

Last Survey, No. 2432Port of IronClassed A. 1.

The present Condition of the

Decks goodWaterways "Comings "Upper Deck Beams & Fastenings "Lower Deck Beams & Fastenings "Planksheers "Sheerstrakes "Topsides "Wales "Plank (Bottom) and Counter "Treenails knets goodBreasthooks and Stenson "Transoms, Pointers, and Crutches "Timbers of the Frame at the Openings "Ditto ditto at other places "Keelsons "Clamps and Shelves "Ceiling "Rudder repairedCopper compos. When put on ironWindlass and Capstan goodPumps "Boats "Masts, Yards, &c. "Sails "Anchors, No. of 6Cables sufficient in size & lengthHawsers and Warps goodStanding and Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways is good

Placed in dry dock & examined all outside & inside as far as practicable and found all below deck in good condition with the exception of the rudder requiring repairing & redubbing and some rivets near the heel of stern-post were found defective. The necessary repairs were completed, bottom cleaned & repainted. The vessel is in very good condition & worth continuation of class.

Committee's Minute 28th October 1879

Character assigned

Fees received £3.3.0Certificate "Certificate (if required). yes

No.

Survey held at

Date

18

on the

Master

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute

18

Character assigned



© 2019

Lloyd's Register
Foundation