

## ANNUAL SURVEYS.

No. 3869 Survey held at Bristol Date, first Survey 31<sup>st</sup> Oct - Last Survey 31<sup>st</sup> Oct 1879  
 No. in Reg. Book. on the S.S. "Belsize" Master Geo Elbridge  
249 Tonnage 1442 Built at Sunderland When built 1878 11 Mo  
 By whom built Thompson Owners Culliford & Clark  
 Port belonging to Sunderland Destined Voyage New York  
 If Surveyed Afloat or in Dry Dock Cleaning & Painting Bottom

Last Survey, No. 22352 Port of Irish Classed 100 A 1  
 Years assigned. 12.78  
 Character in Register Book.  
 Present Condition of the Decks Good Treennails Good Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Ship's Beams & Fastenings " Timbers of the Frame at the Openings "  
 Planks & Fastenings " Ditto ditto at other places "  
 Report on Ship No. 3869 Keelsons Double Bottom  
 Report on Machinery " Clamps and Shelves "  
 Ceiling " Rudder "  
 Copper or Y.M. Coating When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

*This vessel has been placed in Graving Dock, the Bottom scraped & coated with 2 coats of Rahjens Patent, she is appearing in good condition & is in my opinion eligible to remain as classed.*

Committee's Minute 4th November, 1879. Davidson  
 Character assigned 100 A 1 J.B.W. Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 3870 Survey held at Bristol Date, first Survey 29<sup>th</sup> Oct - Last Survey 6<sup>th</sup> Nov 1879  
 No. in Reg. Book. on the Bk "Coronilla" Master William Davies  
1325 Tonnage 524 Built at Liverpool When built 1865 1 Mo  
 By whom built Grans Owners Gambles  
 Port belonging to Liverpool Destined Voyage Singapore  
 If Surveyed Afloat or in Dry Dock Cleaning & Painting Bottom

Last Survey, No. 19208 Port of Irish Classed S.S. No 3.77  
 Years assigned. 9.77  
 Character in Register Book.  
 Present Condition of the Decks Good Treennails Good Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder Overhauled  
 Copper or Y.M. Coating When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

*This vessel has been placed in Graving Dock, the Bottom scraped & coated with 2 coats - White Zinc & 1 Do Zinc & Sallow, the Rudder lifted & overhauled, she is appearing in good condition & is in my opinion eligible to remain as classed.*

Committee's Minute 4th November, 1879. Davidson  
 Character assigned 100 A 1 J.B.W. Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18