

ANNUAL SURVEYS.

24981

Dec 19/11/79

in Reg
Book
29

No. 26739

Survey held at Liverpool

Date 20th Sept to 10th Nov 1879

on the Bk. Corrientes

Master Jones

Tonnage 599 Built at Sunderland

When built 1864-1 mo

By whom built Oswald


Owners Shallcross & Higham

Port belonging to Liverpool

Destined Voyage Adelaide

If Surveyed Afloat or in Dry Dock

Prices Dry Dock



Last Survey, No. 19592 Port of Trow

Classed *A1
11.77
S.S. Liv. No 3-77

The present Condition of the

Decks	<u>good</u>	Ironails <u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>Complete & good</u>
Waterways	"	Breasthooks and Stenson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers	"	Clamps and Shelves	"	Anchors No. of	"
Sheerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper <u>Cement</u> When put on <u>64/1.77.</u>	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

This vessel has now been placed in repairing dock, the bottom cleaned & recoated, is in good condition & eligible in my opinion to remain as classed

Committee's Minute Liverpool 18 Nov^r 1879

Character assigned

*A1

Geo. W. Cooper

Certificate (if required)

IRON 488-0481

No. 26739 Survey held at Liverpool

Date 3 Oct^r to 19th Oct 1879

on the Bk. Olano

Master Ysopirna

Tonnage 400 Built at Belfast

When built 1863-9 mo

By whom built Harland

Owners Olaus Larunaga H^o

Port belonging to Bilbao

Destined Voyage Barcelona via Cardiff

If Surveyed Afloat or in Dry Dock

Prices Dry Dock



Last Survey, No. 18542 Port of Trow

Classed *A1
6.47
S.S. Liv. No 3-76

The present Condition of the

Decks	<u>good</u>	Ironails <u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>Complete & good</u>
Waterways	"	Breasthooks and Stenson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers	"	Clamps and Shelves	"	Anchors No. of	"
Sheerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper <u>Cement</u> When put on <u>63</u>	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

This vessel has now been placed in repairing dock, the bottom cleaned and recoated, is in good condition & eligible, in my opinion, to remain as classed.

Committee's Minute Liverpool 18 Nov^r 1879

Character assigned

*A1

Geo. W. Cooper

Certificate (if required)

