

ANNUAL SURVEYS.

24991

Rec 13/11/11
1879

No. 2651 Survey held at Belfast

Date 6 Oct

1879

On the S.S. "Amelia"

Master

Seaton

Tonnage 1090

Built at

S. Shields

When built

1873 - 5 mo

By whom built

Scott

Owners

Hutchinson & Mac Intyre

Port belonging to

S. Shields

Destined Voyage

✓

If Surveyed Afloat or in Dry Dock

dry dock

Last Survey, No. 22180 Port of Iron

Classed 90 A.I. 11.78

S.S. Merc. No 1-77.

The present Condition of the

Decks	good	Trunnels	Rivets	good	Windlass and Capstan	good
Waterways	—	Breasthooks and Stemson	—	—	Pumps	—
Comings	—	Transoms, Pointers , and Crutches	—	—	Boats	4 N —
Upper Deck Beams & Fastenings	—	Timbers of the Frame	where seen	good	Masts, Yards, &c.	—
Lower Deck Beams & Fastenings	—	Keelsons	—	—	Sails	—
Planksheers	—	Clamps and Shelves	—	—	Anchors No. of	3 B — 1 S — 2 K
Sheerstrakes	—	Ceiling	—	—	Cables	good
Topsides	—	Rudder	—	—	Hawsers and Warps	—
Wales	—	Copper	Paint	When put on	Standing & Running Rigging	—
Plank (Bottom) and Counter	—					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good

Vessel placed in dry dock, bottom cleaned and painted, several plates in rudder renewed, defective ceiling repaired and cemented in. This vessel is in good condition and eligible in my opinion to remain classed 90 A.I.

Committee's Minute 14th November, 1879,

Character assigned

90 A.I. TRW

No. J. W. Scullard
Certificate (if required)

No. 323 Survey held at Belfast

Date 4 Nov

1879

On the S.S. "Italia"

Master

J. W. Mullan

Tonnage 245

Built at

Greenock

When built

1869, 7th

By whom built

Scott

Owners

Belfast Steam Ship Co Ltd

Port belonging to

Belfast

Destined Voyage

Coasting

If Surveyed Afloat or in Dry Dock

dry dock.

Last Survey, No. 22576 Port of Iron

Classed B.I. 1.79

S.S. No 2-76

The present Condition of the

Decks	good	Trunnels	Rivets	good	Windlass and Capstan	good
Waterways	—	Breasthooks and Stemson	—	—	Pumps	—
Comings	—	Transoms, Pointers , and Crutches	—	—	Boats	2 N —
Upper Deck Beams & Fastenings	—	Timbers of the Frame	—	—	Masts, Yards, &c.	—
Lower Deck Beams & Fastenings	—	Keelsons	—	—	Sails	—
Planksheers	—	Clamps and Shelves	—	—	Anchors No. of	3 B — 1 S — 2 K
Sheerstrakes	—	Ceiling	—	—	Cables	Part seen good
Topsides	—	Rudder	—	—	Hawsers and Warps	—
Wales	—	Copper	Paint	When put on	Standing & Running Rigging	—
Plank (Bottom) and Counter	—					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good

Vessel placed in dry dock, bottom cleaned and painted. She is in good condition and eligible in my opinion to remain classed B.I.

Committee's Minute 14th November, 1879,

Character assigned

B.I. TRW

No. J. W. Scullard
Certificate (if required)

IRON 488-0493