

ANNUAL SURVEYS.

No. 267³⁷ Survey held at Liverpool Date, first Survey Oct 16th Last Survey Oct 20th 1879
No. in on the Ship "Duncow" Master T. P. Large
Reg. Book. 524 Tonnage 1635 Built at Sunderland When built 1878 - 7 mo
By whom built Doxford Owners J. Houston
Port belonging to Liverpool Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 21699 Port of Liverpool Classed 100 AI Years assigned. 9.78 Character in Register Book.
Present Condition of the
Decks Good Treenails Rivets Good
Waterways 4 Breasthooks and Stems 4 Windlass and Capstan Good
Comings 4 Transoms, Pointers, and Crutches 4 Pumps 4
Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4 Boats 4
Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4 Masts, Yards, &c. 4
Planksheers 4 Keelsons 4 Condition, how ascertained from on board
Sheerstrakes 4 Clamps and Shells 4 Sails Good
Topsides 4 Ceiling 4 Anchors, No. of 3 B - 18 - 2 K
Wales 4 Rudder 4 Cables 11 cent Good
Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 78 Hawesers and Warps and
Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Standing and Running Rigging Sufficient
General Observations, Opinion as to Class, &c. Cargo and Main Hatchways Good Hatches Good

Bottom sighted cleaned and coated with paint, & the vessel being now in a good and efficient condition is eligible in my opinion to remain as classed -

Committee's Minute Liverpool Nov^r 12th 1879
Character assigned 100 AI

T. Shilston

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) 18

No. ✓ Survey held at Liverpool Date, first Survey Oct 21st Last Survey Oct 21st 1879
No. in on the Ship "Bay of Cadiz" Master J. Catter
Reg. Book. 137 Tonnage 1626 Built at Glasgow When built 1878 - 12 mo
By whom built Thomson Owners J. & G. Bullock
Port belonging to London Destined Voyage Rangoon
If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 22818 Port of Liverpool Classed 100 AI Years assigned. 2.79 Character in Register Book.
Present Condition of the
Decks Good Treenails Rivets Good
Waterways 4 Breasthooks and Stems 4 Windlass and Capstan Good
Comings 4 Transoms, Pointers, and Crutches 4 Pumps 4
Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4 Boats 4
Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4 Masts, Yards, &c. 4
Planksheers 4 Keelsons 4 Condition, how ascertained from on board
Sheerstrakes 4 Clamps and Shells 4 Sails Good
Topsides 4 Ceiling 4 Anchors, No. of 3 B - 18 - 2 K
Wales 4 Rudder 4 Cables 11 cent Good
Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 78 Hawesers and Warps and
Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Standing and Running Rigging Sufficient
General Observations, Opinion as to Class, &c. Cargo and Main Hatchways Good Hatches Good

Bottom sighted cleaned and coated with paint and the vessel being now in a good and efficient condition is eligible in my opinion to remain as classed -

Committee's Minute Liverpool Nov^r 14th 1879
Character assigned 100 AI

T. Shilston

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) 18

Winrow
Pay of Lady
26737.



© 2019

Lloyd's Register
Foundation