

ANNUAL SURVEYS.

25027
Per 24/11/79

No. 4280 Survey held at Dundee.

Date 11th November 1879.

on the S. Ship "Carradale"

Master M'Diarmid

Tonnage 1242 Built at Glasgow

When built 1877 - 4 mo.

By whom built Dobie

Owners J. Manford.

Port belonging to Glasgow.

Destined Voyage Shields in ballast.

If Surveyed Afloat or in Dry Dock In dry dock with ballast on board.

Last Survey, No. 21621 Port of Iron

Classed 100A-1; 8.78.

The present Condition of the

Decks	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Waterways	Butler	Breasthooks and Stemson			Pumps	
Comings		Transoms, Pointers, and Crutches			Boats	4 No.
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings			Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places			Sails	
Planksheers		Keelsons	Where exposed	Good	Anchors	No. of 3 B. 15. 2 K
Sheerstrakes		Clamps and Shelves	Stringers		Cables	
Topsides		Ceiling	Where exposed		Hawsers and Warps	
Wales		Rudder	Good & efficient		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper	Cement	When put on 1877.		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

Vessel placed on blocks, keel, bottom & sides cleaned down and examined, rebushed the timbers and recoated bottom & sides.

This vessel is now in a good and efficient state, fit for the conveyance of dry & perishable goods to & from all parts of the world, and in my opinion eligible to remain as Classed.

Committee's Minute 25th November, 18 79.

Character assigned 100A-1

JTBW J.L. Dunnet

Certificate (if required)

No. Survey held at Date 18

on the Master

Tonnage Built at When built

By whom built Owners

Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of

Classed

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors
Sheerstrakes	Clamps and Shelves	No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper	When put on
		Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18

Character assigned