

# ANNUAL SURVEYS.

No. 3872 Survey held at London Date, first Survey Nov 18<sup>th</sup> Last Survey Dec 9<sup>th</sup> 1875  
 No. in on the S Lochee Master J Rachum  
 Reg. Book. 627 Tonnage 1728 Built at Dundee When built 1874 S.M.  
 By whom built Stephen Owners J Bruce &  
 Port belonging to Dundee Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 22409 Port of India  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stenson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom is Coated

Classed 100A 1.75  
 SS Lo M-1-75

*She is now in good condition and eligible to remain as classed.*

Committee's Minute 16th December 1879.  
 Character assigned 100A DBW

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 402 Survey held at London Date, first Survey Nov 14 Last Survey Nov 25 1875  
 No. in on the S Norval Master Halliday  
 Reg. Book. 402 Tonnage 1427 Built at Sunderland When built 1873 S.M.  
 By whom built Watson Owners J. O. Hunter & Henry  
 Port belonging to Greenock Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 23804 Port of Iran  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stenson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom is Coated

Classed 100A 5.75  
 SS Lo M-1-78

*She is now in good condition and eligible to remain as classed.*

Committee's Minute 16th December 1879.  
 Character assigned 100A DBW

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18