

\* 25264

# Report of Survey for Repairs of Engines and Boilers.

[No. of 22nd 12/79]

No. \_\_\_\_\_  
No. in Reg. Book. 292 Survey held at London on the S.S. Rhone Date, first Survey Nov 22 Last Survey Dec 9<sup>th</sup> 1879 Master \_\_\_\_\_

Built at Sunderland When built 1868  
Tons 868 Owners W. G. Westcott Port belonging to London Classified \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. 90A1

Diameter of Cylinder 30 1/2 Length of Stroke 34 Pressure of Steam 53 lbs Registered Horse Power 200  
Engines made at Mullwall When made 1871  
By whom made Mullwall Dock Eng'rs

Particulars of Repairs and Examination Vessel placed in Dry dock, and a new stern tube fitted. Tail end shaft fitted with brass liner where working in stern gland, shaft replaced and propeller refitted.

The water tubes in the Combustion chambers renewed as it was found impossible to clean them.

The machinery of this vessel is now in good order and in my opinion renders her eligible to remain as classed.

In subsequent Repairs and Examinations, to be cleared.

The Amount of Fee ... £ \_\_\_\_\_ received by me, }  
Certificate (if required) ... £ \_\_\_\_\_ 187 }  
(Travelling Expenses, if any, £ \_\_\_\_\_)

James J. Muller  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_



RON489-0319