

ANNUAL SURVEYS.

25294

(Received at London Office, 30. 12. 79)

No. 20692. Survey held at London

Date, first Survey 27th Novbr. Last Survey 19th Decbr. 1879

No. in Reg. Book. 489 on the Ship "Blackadder"

Master H. Allan

Tonnage 917 970 872 Built at London

When built 1870 2nd mo

By whom built Maudsley

Owners Hillis & Son

Port belonging to London

Destined Voyage Sydney

If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 20692 Port of Iron

Classed

Years assigned.

Character in Register Book.

* A1

3.78

Present Condition of the Decks

	Good	Treenails	Rivets	Good		
Waterways	do			do	Breasthooks and Stemson	do
Comings	do			do	Transoms, Pointers, and Crutches	do
Upper Deck Beams & Fastenings	do			do	Timbers of the Frame at the Openings	do
Lower Deck Beams & Fastenings	do			do	Ditto ditto at other places	do
Planksheers	do			do	Keelsons	do
Sheerstrakes	do			do	Clamps and Shelves	do
Topsides	do			do	Ceiling	do
Wales	do			do	Rudder	do
Plank (Bottom) and Counter	do			do	Copper or F.M. Paint When put on now	do
Engine Room Skylights				do	Caulking of Bottom, Deck, & Waterways	good
Coal Bunker, Openings, Lids, &c.				do	Scuppers	do
General Observations, Opinion as to Class, &c.				do	Cargo and Main Hatchways	good
				do	Hatches	do

S. I. Lon. No 2-78

Windlass and Capstan Good

Pumps do

Boats 4 in number do

Masts, Yards, &c. do

Condition, how ascertained from deck & enquiry

Sails do

Anchors, No. of 3 B. 1st. 2nd do

Cables part seen do

Hawsers and Warps do

Standing and Running Rigging do

Mizen Mast renewed. - Some ceiling in hold renewed. -

Surveyed with ballast in way of main hatch. -

Bottom cleaned & repainted. -

This vessel is in good condition & eligible in my opinion to remain as classed. -

Committee's Minute

2nd January,

1880.

W. Paulsen.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. Survey held at London

Date, first Survey 17th Decbr. Last Survey 22nd Decbr. 1879. -

No. in Reg. Book. 295 on the Bk. "Rialto"

Master J. Williamson

Tonnage 1166 1212 1115 Built at Sunderland

When built 1869 2nd mo

By whom built Oswald

Owners Merch^t Shipp. Comp^y. -

Port belonging to London

Destined Voyage Not fixed.

If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 22950 Port of Iron

Classed

Years assigned.

Character in Register Book.

* A1

10.78

Present Condition of the Decks

	Good	Treenails	Rivets	Good		
Waterways	do			do	Breasthooks and Stemson	do
Comings	do			do	Transoms, Pointers, and Crutches	do
Upper Deck Beams & Fastenings	do			do	Timbers of the Frame at the Openings	do
Lower Deck Beams & Fastenings	do			do	Ditto ditto at other places	do
Planksheers	do			do	Keelsons	do
Sheerstrakes	do			do	Clamps and Shelves	do
Topsides	do			do	Ceiling	do
Wales	do			do	Rudder	do
Plank (Bottom) and Counter	do			do	Copper or F.M. Paint When put on now	do
Engine Room Skylights				do	Caulking of Bottom, Deck, & Waterways	good
Coal Bunkers, Openings, Lids, &c.				do	Scuppers	do
General Observations, Opinion as to Class, &c.				do	Cargo and Main Hatchways	good
				do	Hatches	do

S. I. Lon. No 2-78

Windlass and Capstan Good

Pumps do

Boats 4 in number do

Masts, Yards, &c. do

Condition, how ascertained from deck & enquiry

Sails do

Anchors, No. of 3 B. 1st. 2nd do

Cables part seen do

Hawsers and Warps do

Standing and Running Rigging do

Rudder pintles bushed. - Main top gallant mast repaired. -

Bottom cleaned & repainted. -

This vessel is in good condition & eligible in my opinion to remain as classed. -

Committee's Minute

2nd January,

1880.

W. Paulsen.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

Blanchard
Rialto

ANNUAL SURVEYS



© 2019

Lloyd's Register
Foundation