

ANNUAL SURVEYS.

25299

No. 26797 Survey held at Liverpool Date 28 Nov: to 9 Dec 1879
 on the S.S. Castello Master Anderson
 Tonnage 1403 Built at Stockton When built 1877 - 10 mo.
 By whom built Richardson Owners Clarkson & Co
 Port belonging to London Destined Voyage Singapore
 If Surveyed Afloat or in Dry Dock Sunder Dry Dock

Last Survey, No. 22914 Port of Iron Classed 100 A1
 The present Condition of the

Decks <u>good</u>	Iron <u>Rails</u> <u>good</u>	Windlass and Capstan <u>Complete good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B 1 S 2 H</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>Complete</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>good</u>
Wales <u>"</u>	<u>Copper Cement</u> When put on <u>77</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good
 This vessel has now been placed in graving dock, the bottom cleaned & recoated, is in good condition & eligible in my opinion, to remain as closed
 Committee's Minute Liverpool Dec: 24th 1879
 Character assigned 100 A1.
Geo. T. Cooper
 Certificate (if required)

No. ✓ Survey held at Liverpool Date 24 Nov: to 27 Nov 1879
 on the S.S. Fernwood Master B. Seighton
 Tonnage 1203 Built at Newcastle When built 1877 - 4 mo.
 By whom built Swan Owners J. D. Milburn
 Port belonging to London Destined Voyage Aden via Cardiff
 If Surveyed Afloat or in Dry Dock Sunder Dry Dock

Last Survey, No. 24644 Port of Iron Classed 100 A1
 The present Condition of the

Decks <u>good</u>	Iron <u>Rails</u> <u>good</u>	Windlass and Capstan <u>Complete good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B 1 S 2 H</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>Complete</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>good</u>
Wales <u>"</u>	<u>Copper Cement</u> When put on <u>77</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good
 This vessel has now been placed in graving dock & some slight repairs to bulwarks & deck work on the starboard side have now been done. The bottom recoated. The vessel is in good condition & eligible in my opinion
 Committee's Minute Liverpool Dec: 24th 1879
 Character assigned 100 A1.
Geo. T. Cooper
 Certificate (if required)

180489-0358

Bastello^{ss.}

Ternwood^{ss.}

367 9^s
26797



© 2019

Lloyd's Register
Foundation