

ANNUAL SURVEYS.

25409

(Received at London Office, ...)

No. 38490 Survey held at London Date, first Survey 7th Jan Last Survey 8th Jan 1880
 on the Iron S.S. "Perim" Master Jas Scott
 Tonnage 1016 Built at Glasgow When built 1877-4 mo
 By whom built Lon & Glas^{co} Owners R. W. Fousens & Co
 Port belonging to London Destined Voyage Medit^a
 If Surveyed Afloat or in Dry Dock Commercial dry dock

Last Survey, No. 22124 Port of Iron Classed 100 A1
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways --- Breasthooks and Stems ---
 Comings --- Transoms, Pointers, and Crutches ---
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings ---
 Lower Deck Beams & Fastenings --- Ditto ditto at other places ---
 Planksheers --- Keelsons ---
 Sheerstrakes --- Clamps and Shelves ---
 Topsides --- Ceiling ---
 Wales --- Rudder ---
 Plank (Bottom) and Counter --- Copper or Y.M. Cement When put on 1877
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom repainted. She appears well seen in good condition and in my opinion may continue as Classed

Committee's Minute 13th January, 1880.Character assigned 100 A1

Wm E. Leaver
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1880

No. 363 Survey held at London Date, first Survey 29th Dec 79 Last Survey 3rd Jan 1880.
 on the Ship "Leucadia" Master W. McEarns
 Tonnage 896 Built at Aberdeen When built 1870-3 mo.
 By whom built Good Owners A. Nicol & Co
 Port belonging to Aberdeen Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Ratcliff Cross dry dock

Last Survey, No. 24357 Port of Iron Classed A.1.
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways --- Breasthooks and Stems ---
 Comings --- Transoms, Pointers, and Crutches ---
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings ---
 Lower Deck Beams & Fastenings --- Ditto ditto at other places ---
 Planksheers --- Keelsons ---
 Sheerstrakes --- Clamps and Shelves ---
 Topsides --- Ceiling ---
 Wales --- Rudder ---
 Plank (Bottom) and Counter --- Copper or Y.M. Cement When put on 1870
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights --- Coal Bunker, Openings, Lids, &c. --- Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. Bottom sighted cleaned and coated with Paint and Tallow, some defective ceiling in the fore hold renewed with 2 1/2 Pine. This vessel is now in good and efficient condition and in my opinion eligible to remain as Classed.

Committee's Minute 13th January, 1880.Character assigned A1

Thos Wm Blayell
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1880