

Report of Survey for Repairs of Engines and Boilers.

No. 25428
 No. in Reg. Book. 1843 Survey held at London Date, first Survey Dec 24, 1877 Last Survey Jan 14th 1880
 on the S.S. "Viceroy" Master R. Black & Murdoch
 Built at London When built 1871
 Tons 2450 Owners R. & S. Green Port belonging to London Classified 100A1
 Character in Register Book. 5.79
 YEAR.

Diameter of Cylinder 38" + 66" Engines made at London When made 1871
 Length of Stroke 39"
 Pressure of Steam 60 lbs. By whom made Ravenhill, Hodgson & Co
 Registered Horse Power 240

Particulars of Repairs and Examination Vessel placed in Dry Dock and propeller & sea connections examined and found to be in good condition. Cylinders & slides examined and found in good order. Crank shaft examined and found sound and in good condition. Main Boilers examined. a new furnace crown plate fitted in one of aft furnaces of port boiler. Boilers found in good condition. Safety valves taken off and Adams' patent spring valves fitted. Boilers & Engines tried under steam, and found to work well. The safety valves being found to blow off at the required loaded pressure.

The machinery & boilers of this vessel are now in good order and safe working condition, and in our opinion render the vessel eligible to have the notification B & M. 1. 80 recorded in the Register Book.

Entry Fee. 21/1/40 3 0 0
 Amount of Fee £ 3 : 3 : 0 received by me, C. R. A.
 Certificate (if required) £ : 5 : 0 22 Jan 1880
 Travelling Expenses, if any, £

Committee's Minute 22nd January 1880
B & M. 1. - 1. 80 to be recorded
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.
G. Stoddart & J. T. Milson

