

ANNUAL SURVEYS.

(Received at London Office, 25/3/80)

No. 14652 Survey held at Newcastle Date, first Survey and Last Survey 27 January 1880
No. in on the Iron RR. "Barracouta" Master H. E. Barber
Reg. Book. 189 Tonnage 610 Built at Liverpool When built 1864 - 7 mo
By whom built Evans Owners W. Killey & Co
Port belonging to Liverpool Destined Voyage Valparaiso
If Surveyed Afloat or in Dry Dock St. Peters Dry Dock

Last Survey, No. 22545 Port of Iron Classed 179 Years assigned. # A1 Character in Register Book.
Present Condition of the
Decks Good. Treennails Planks Good. S.S. Liv- No 3-76.
Waterways do Breasthooks and Stemson do. Windlass and Capstan Good
Comings do Transoms, Pointers, and Crutches do. Pumps do.
Upper Deck Beams & Fastenings do. Timbers of the Frame at the Openings do when they could be seen Boats do.
Lower Deck Beams & Fastenings do. Ditto ditto at other places At Cargo outboard Masts, Yards, &c. do.
Planksheers do. Keelsons do. Condition, how ascertained from the deck & inquiry
Sheerstrakes do. Clamps and Shelves Stringers do. Sails Sufficient & Good
Topsides do. Ceiling do. Anchors, No. of do.
Wales do. Rudder do. Cables do.
Plank (Bottom) and Counter do. Copper or Y.M. ✓ When put on ✓ Hawsers and Warps do.
Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Secure Hatches Good.
General Observations, Opinion as to Class, &c.

This vessel's bottom has now been cleaned and recoated. She appears to be in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute

9th January, 1880

J. H. Cooke.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in on the Master
Reg. Book. Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed Years assigned. Character in Register Book.
Present Condition of the
Decks Treennails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18