

# ANNUAL SURVEYS.

25440

No. 2668 Survey held at Belfast Date, first Survey ✓ Last Survey 22 January 1880  
 No. in on the Reg. Book. 122 Tonnage 226,356,323 Built at Belfast Master G. Farmer  
 By whom built Harland Owners Harland & Co  
 Port belonging to Belfast Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Dry dock.

Last Survey, No. 22478 Port of Iron Classed 100 H.I.  
 Present Condition of the Decks good Treenails Rivets good  
 Waterways — Breasthooks and Stemson —  
 Comings — Transoms, ~~Pointers~~, and Crutches —  
 Upper Deck Beams & Fastenings — ~~Timbers~~ of the Frame at the Openings —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places —  
 Planksheers — Keelsons good  
 Sheerstrakes — Clamps and Shelves —  
 Topsides — Ceiling —  
 Wals — Rudder —  
 Plank (Bottom) and Counter — Copper or Y.M. Paint When put on now  
 Caulking of Bottom, Deck, & Waterways good  
 Windlass and Capstan good  
 Pumps —  
 Boats —  
 Masts, Yards, &c. —  
 Condition, how ascertained from deck  
 Sails good  
 Anchors, No. of 32-15-16  
 Cables good  
 Hawesers and Warps —  
 Standing and Running Rigging —  
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers — Cargo and Main Hatchways good Hatches —  
 General Observations, Opinion as to Class, &c.

Vessel placed in dry dock. bottom and keel sighted, bottom cleaned and painted. This vessel is in good condition and eligible in my opinion to remain classed 100 H.I.

Committee's Minute Tuesday, February, 3rd 1880.  
 Character assigned 100 H.I. J.W. Lullard  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —

No. — Survey held at — Date, first Survey — Last Survey — 18 —  
 No. in on the Reg. Book. — Tonnage — Built at — Master —  
 By whom built — Owners —  
 Port belonging to — Destined Voyage —  
 If Surveyed Afloat or in Dry Dock —

Last Survey, No. — Port of — Classed —  
 Present Condition of the Decks — Treenails —  
 Waterways — Breasthooks and Stemson —  
 Comings — Transoms, Pointers, and Crutches —  
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places —  
 Planksheers — Keelsons —  
 Sheerstrakes — Clamps and Shelves —  
 Topsides — Ceiling —  
 Wals — Rudder —  
 Plank (Bottom) and Counter — Copper or Y.M. — When put on —  
 Caulking of Bottom, Deck, & Waterways —  
 Windlass and Capstan —  
 Pumps —  
 Boats —  
 Masts, Yards, &c. —  
 Condition, how ascertained —  
 Sails —  
 Anchors, No. of —  
 Cables —  
 Hawesers and Warps —  
 Standing and Running Rigging —  
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers — Cargo and Main Hatchways — Hatches —  
 General Observations, Opinion as to Class, &c.

Committee's Minute 18  
 Character assigned — J.W. Lullard  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —