

ANNUAL SURVEYS.

No. 28,847 Survey held at London Date, first Survey Jan 19th Last Survey Jan 23rd 1880
 No. in on the SS Grantully Castle Master
 Reg. Book. 27 Tonnage 2234 Built at Glasgow When built 1875-11/11
 Supp By whom built Barclay Owners J Burrie
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Green's Dry Dock

Last Survey, No. 25323 Port of Iron

Present Condition of the
Decks

Good
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Rivets
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings
 Ditto ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper or Y.M. Coated When put on Now
 Caulking of
 Bottom, Deck, & Waterways

Good
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of 3 Bbs. 12 & 14 lbs
 Cables Part on 12
 Hawseers and Warps
 Standing and Running Rigging

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches
 General Observations, Opinion as to Class, &c. Bottom & coated

She is now in good condition
and eligible to remain as classed.

Committee's Minute Friday, January, 30th 1880

Character assigned 100A

Senhouse Martinide
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at London Date, first Survey Jan 13th Last Survey Jan 14th 1880
 No. in on the S Tilghurst Master E J Blake
 Reg. Book. 339 Tonnage 1527 Built at Sumbarton When built 1877.5m
 By whom built Mr Millan Owners W R Price
 Port belonging to London Destined Voyage Liverpool & Bombay
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 21994 Port of Iron

Present Condition of the

Good
 Decks
 Waterways
 Comings
 Upper Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Planksheers
 Sheerstrakes
 Topsides
 Wales
 Plank (Bottom) and Counter

Rivets
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings
 Ditto ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper or Y.M. Coated When put on Now
 Caulking of
 Bottom, Deck, & Waterways

Good
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of 3 Bbs. 12 & 14 lbs
 Cables Part on 12
 Hawseers and Warps
 Standing and Running Rigging

Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches
 General Observations, Opinion as to Class, &c. Bottom & coated

She is now in good condition
and eligible to remain as classed.

Committee's Minute Friday, January, 30th 1880

Character assigned 100A

Senhouse Martinide
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18