

No. 187<sup>+</sup> Survey held at Batavia Date, first Survey 25541 Last Survey 30<sup>th</sup> October 1879

No. in Reg. Book. 997 on the British Barque Clyde Bank Master Bourie  
Tonnage 863 Built at Dumbarton When built 1877  
By whom built Birrell Owners C. C. McFarlane  
Port belonging to Glasgow Destined Voyage Channel for orders  
If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 23461 Port of Iron

Present Condition of the Decks

Waterways

Comings

per Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M.

Caulking of Bottom, Deck, & Waterways

When put on

Iron

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan good condition

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchor, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

good condition

good as far as with

Classed

Years assigned.

100

Character in Register Book.

A. 1.

6.38

Committee's Minute

Character assigned

27th January,

1880.

100A1

VBW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

40 Paid

30<sup>th</sup> October 1879.

MPB