

# ANNUAL SURVEYS.

25569

(Received at London Office, 12/2/80)

No. 14694 Survey held at Newcastle Date, first Survey 27<sup>th</sup> Jan Last Survey 27<sup>th</sup> Jan 1880  
 No. in Reg. Book. 896 on the S.S. "Lutetia" Master E. Ablett  
 Tonnage 516 Built at Sunderland When built 1877 12 Mo.  
 By whom built Thompson Owners Bell & Symonds  
 Port belonging to Newcastle Destined Voyage France  
 If Surveyed Afloat or in Dry Dock on Wallsend Slipway

Last Survey, No. 25225 Port of Jan Classed 90A1  
 Present Condition of the Decks Good Treenails Reinb Good  
 Waterways " Breasthooks and Stemson ✓  
 Comings " Transoms, Pointers, and Crutches ✓  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers ✓ Keelsons "  
 Sheerstrakes " Clamps and Shelves ✓  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Paint - When put on Now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

The bottom of this vessel has been cleaned and coated, she is appearing in good condition & eligible in my opinion to remain as classed.

Committee's Minute Friday, February, 13th 1880 L Davidson  
 Character assigned 90A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) TTW Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 No. in Reg. Book. \_\_\_\_\_ on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. Paint - When put on \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

