

ANNUAL SURVEYS.

25613

No. 38829 Survey held at London Date, first Survey Jan 2^d Last Survey Jan 21st 18 80
 on the SS ~~Malman Castle~~ Valencia Master C Young
 Tonnage 1554 Built at Glasgow When built 1872 4M
 By whom built Burchar Owners J Currie & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Thames Iron Works & Co

Last Survey, No. 23152 Port of Iron Classed 100A 6-75
 Present Condition of the
 Treenails good Rivets good
 Breasthooks and Stemson good
 Transoms, Pointers, and Crutches good
 Timbers of the Frame at the Openings good
 Ditto ditto at other places good
 Keelsons good
 Clamps and Shelves good
 Ceiling good
 Rudder good
 Copper or Y.M. Coated When put on now
 Caulking of good
 Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps good
 Boats good
 Masts, Yards, &c. good
 Condition, how ascertained From Stk
 Sails good
 Anchors, No. of 3 Bbs. St & Redges
 Cables Part on Stk good
 Hawsers and Warps good
 Standing and Running Rigging good
 Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom &c coated.

She is now in good condition and eligible to remain as classed.
 Committee's Minute 23rd January, 18 80
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale
 Certificate (if required) 5/- Paid 22/5 18 80
TJBW

No. Survey held at London Date, first Survey Jan 17th Last Survey Jan 15th 18 80
 on the SS Warwick Castle Master Robson
 Tonnage 1892 Built at Glasgow When built 1877 8M
 By whom built 2957 Napier Owners J Currie & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Thames Iron Works & Co

Last Survey, No. 25122 Port of Iron Classed 100A 10-77
 Present Condition of the
 Treenails good Rivets good
 Breasthooks and Stemson good
 Transoms, Pointers, and Crutches good
 Timbers of the Frame at the Openings good
 Ditto ditto at other places good
 Keelsons good
 Clamps and Shelves good
 Ceiling good
 Rudder good
 Copper or Y.M. Coated When put on now
 Caulking of good
 Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps good
 Boats good
 Masts, Yards, &c. good
 Condition, how ascertained From Stk
 Sails good
 Anchors, No. of 3 Bbs. St & Redges
 Cables Part on Stk good
 Hawsers and Warps good
 Standing and Running Rigging good
 Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom &c coated.

She is now in good condition and eligible to remain as classed.
 Committee's Minute 23rd January, 18 80.
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale
 Certificate (if required) 5/- Paid 22/5 18 80
TJBW