

ANNUAL SURVEYS. 25640

(Received at London Office, 8/3/80)

No. 14445 Survey held at S. Shields Date, first Survey 10th Feb Last Survey 10th Feb 1880
 No. in Reg. Book. on the Iron S.S. "Hawthorns" Master Coleman
 Tonnage 473 Built at Newcastle When built 1861 8 mo
 By whom built Palmer Owners J. Fenwick & Son
 Port belonging to London Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Wilsons Dry Dock

Last Survey, No. 25362 Port of Liverpool

Classed ✓ Years assigned. 1,80 Character in Register Book. A1

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>D</u>	Breasthooks and Stemson	<u>D</u>	<u>D</u>	Pumps	<u>D</u>
Comings	<u>D</u>	Transoms, Pointers, and Crutches	<u>D</u>	<u>D</u>	Boats	<u>D</u>
Upper Deck Beams & Fastenings	<u>D</u>	Timbers of the Frame at the Openings	<u>D</u>	<u>D</u>	Masts, Yards, &c.	<u>D</u>
Lower Deck Beams & Fastenings	<u>D</u>	Ditto ditto at other places	<u>D</u>	<u>D</u>	Condition, how ascertained	<u>By examination</u>
Planksheers	<u>D</u>	Keelsons	<u>D</u>	<u>D</u>	Sails	<u>Complete</u>
Sheerstrakes	<u>D</u>	Clamps and Shelves	<u>D</u>	<u>D</u>	Anchors, No. of	<u>Complete</u>
Topsides	<u>D</u>	Ceiling	<u>D</u>	<u>D</u>	Cables	<u>Complete</u>
Wales	<u>D</u>	Rudder	<u>D</u>	<u>D</u>	Hawsers and Warps	<u>Complete</u>
Plank (Bottom) and Counter	<u>D</u>	Copper or Y.M. Paint When put on <u>new</u>	<u>Good</u>	<u>Good</u>	Standing and Running Rigging	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. Bottom sighted, cleaned and repainted.
This vessel is now in good and efficient condition, and in my opinion eligible to remain as classed.

Committee's Minute Tuesday, March, 9th 1880.

Character assigned A1

M. Mowbray
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid ✓ 18 80

No. 648 Survey held at S. Shields Date, first Survey 16th Feb Last Survey 18th Feb 1880
 No. in Reg. Book. on the Iron S.S. "Sicilian" Master Purdy
 Tonnage 886 Built at Hartlepool When built 1877 11 mo
 By whom built Wishy Owners Blair & Co
 Port belonging to Leith Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Jump's dry dock

Last Survey, No. 24133 Port of Liverpool

Classed ✓ Years assigned. 7,79 Character in Register Book. 100 A1

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>D</u>	Breasthooks and Stemson	<u>D</u>	<u>D</u>	Pumps	<u>D</u>
Comings	<u>D</u>	Transoms, Pointers, and Crutches	<u>D</u>	<u>D</u>	Boats	<u>D</u>
Upper Deck Beams & Fastenings	<u>D</u>	Timbers of the Frame at the Openings	<u>D</u>	<u>D</u>	Masts, Yards, &c.	<u>D</u>
Lower Deck Beams & Fastenings	<u>D</u>	Ditto ditto at other places	<u>D</u>	<u>D</u>	Condition, how ascertained	<u>By examination</u>
Planksheers	<u>D</u>	Keelsons	<u>D</u>	<u>D</u>	Sails	<u>Complete</u>
Sheerstrakes	<u>D</u>	Clamps and Shelves	<u>D</u>	<u>D</u>	Anchors, No. of	<u>Complete</u>
Topsides	<u>D</u>	Ceiling	<u>D</u>	<u>D</u>	Cables	<u>Complete</u>
Wales	<u>D</u>	Rudder	<u>D</u>	<u>D</u>	Hawsers and Warps	<u>Complete</u>
Plank (Bottom) and Counter	<u>D</u>	Copper or Y.M. Paint When put on <u>new</u>	<u>Good</u>	<u>Good</u>	Standing and Running Rigging	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. Bottom sighted, cleaned and repainted.
This vessel is now in good and efficient condition, and is in my opinion eligible to remain as classed.

Committee's Minute Tuesday, March, 9th 1880.

Character assigned 100 A1

M. Mowbray
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid ✓ 18 80