

# ANNUAL SURVEYS.

25649  
Rev. 25/2/80

No. 2688<sup>2</sup> Survey held at Liverpool Date Jan 29 1880  
on the Ship "Nagpore" Master Robertson.  
Tonnage 1521 Built at W. Hartlepool When built 1865 - 1 mo  
By whom built Pile Owners Mackinnon Frew & Co  
Port belonging to Liverpool Destined Voyage Calcutta  
If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 23090 Port of Iron Classed \*A1 3.79.  
S.S. Liv No 1.79.

The present Condition of the	Good	Greenails	Rivets.	Good	Windlass and Capstan	Good
Decks						
Waterways	4	Breasthooks and Stemson		4	Pumps	4
Comings	4	Transoms, Pointers, and Crutches		4	Boats	4
Upper Deck Beams & Fastenings	4	Timbers of the Frame		4	Masts, Yards, &c.	4
Lower Deck Beams & Fastenings	4	Keelsons		4	Sails	Good
Planksheers	4	Clamps and Shelves		4	Anchors No. of <u>3B - 1S - 2K</u>	
Sheerstrakes	4	Ceiling		4	Cables <u>pt seen</u>	Good
Topsides	4	Rudder		4	Hawsers and Warps	and
Wales	4	Copper Cement When put on <u>65 pt 74</u>			Standing & Running Rigging	Sufficient
Plank (Bottom) and Counter	4					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good.

Damaged bulwarks, rails & repaired, vessels bottom sighted, cleaned and coated with paint, she is now in a good and efficient condition, eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Feb 24<sup>th</sup> 1880

Character assigned

\*A1.

J. Shilstone.

Certificate (if required)

No. ✓ Survey held at Liverpool Date Jan 31<sup>st</sup> 1880.  
on the Bark "Luke Bruce" Master Luke  
Tonnage 310 Built at Aberdeen When built 1868 - 11 mo  
By whom built Hall Russel & Co Owners J. Harrison & Co  
Port belonging to Liverpool Destined Voyage Africa  
If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 21963 Port of Iron Classed \*A1 9.78.  
S.S. Liv No 2.76.

The present Condition of the	Good	Greenails	Rivets.	Good	Windlass and Capstan	Good
Decks						
Waterways	4	Breasthooks and Stemson		4	Pumps	4
Comings	4	Transoms, Pointers, and Crutches		4	Boats	4
Upper Deck Beams & Fastenings	4	Timbers of the Frame		4	Masts, Yards, &c.	4
Lower Deck Beams & Fastenings	4	Keelsons		4	Sails	4
Planksheers	4	Clamps and Shelves		4	Anchors No. of <u>3B - 1S - 2K</u>	
Sheerstrakes	4	Ceiling		4	Cables <u>pt seen</u>	Good
Topsides	4	Rudder		4	Hawsers and Warps	and
Wales	4	Copper Cement When put on <u>68</u>			Standing & Running Rigging	Sufficient.
Plank (Bottom) and Counter	4					

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

Bottom sighted, cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Feb 24<sup>th</sup> 1880

Character assigned

\*A1

J. Shilstone

Certificate (if required).



Nagpore  
Luke Bruce

26882.



© 2019

Lloyd's Register  
Foundation