

ANNUAL SURVEYS.

25899
Re 22/3/80

No. 607 Survey held at Antwerp Date 9 & 10 March 1880.
 on the Shoon P. S. "Baron Bsh" Master J. Verbiest
 Tonnage 573 Built at Newcastle When built 1875. 5 mo
 By whom built Mitchell Owners Antw. Stev. Ship Co
 Port belonging to Antwerp Destined Voyage Antw - London
 If Surveyed Afloat or in Dry Dock afloat

| | | | |
|--|---|--|--|
| Last Survey, No. <u>2247</u> Port of <u>Ant</u> | | Classed <u>100 A 1</u> S.S. No <u>1-33</u> <u>139</u> | |
| The present Condition of the | | | |
| Decks <u>good</u> | Treenails <u>Pivots</u> <u>good</u> | Windlass and Capstan <u>good</u> | |
| Waterways <u>"</u> | Breasthooks and Stemson <u>"</u> | Pumps <u>"</u> | |
| Comings <u>"</u> | Transoms, Pointers, and Crutches <u>"</u> | Boats <u>"</u> | |
| Upper Deck Beams & Fastenings <u>"</u> | Timbers of the Frame at the Openings <u>"</u> | Masts, Yards, &c. <u>"</u> | |
| Lower Deck Beams & Fastenings <u>"</u> | Ditto ditto at other places <u>"</u> | Sails <u>"</u> | |
| Planksheers <u>"</u> | Keelsons <u>"</u> | Anchors, No. of <u>6</u> | |
| Sheerstrakes <u>"</u> | Clamps and Shelves <u>"</u> | Cables <u>"</u> | |
| Topsides <u>"</u> | Ceiling <u>"</u> | Hawsers and Warps <u>"</u> | |
| Wales <u>"</u> | Rudder <u>"</u> | Standing and Running Rigging <u>"</u> | |
| Plank (Bottom) and Counter <u>"</u> | Copper <u>"</u> When put on <u>"</u> | | |
| General Observations and Opinion, <u>Examined the Vessel at Owners request outside & inside as far as practicable and found all when seen in good condition and the Vessel worthy her present class.</u> | | | |
| Committee's Minute <u>Tuesday, March, 23rd 1880.</u> | | | |
| Character assigned <u>100 A</u> | | | |
| For received L. S. S. O. Certificate <u>MA MS</u> <u>1880</u> Certificate (if required) <u>yes</u> | | | |

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

| | | | |
|---|--|------------------------------------|--|
| Last Survey, No. _____ Port of _____ | | Classed _____ | |
| The present Condition of the | | | |
| Decks _____ | Treenails _____ | Windlass and Capstan _____ | |
| Waterways _____ | Breasthooks and Stemson _____ | Pumps _____ | |
| Comings _____ | Transoms, Pointers, and Crutches _____ | Boats _____ | |
| Upper Deck Beams & Fastenings _____ | Timbers of the Frame at the Openings _____ | Masts, Yards, &c. _____ | |
| Lower Deck Beams & Fastenings _____ | Ditto ditto at other places _____ | Sails _____ | |
| Planksheers _____ | Keelsons _____ | Anchors, No. of _____ | |
| Sheerstrakes _____ | Clamps and Shelves _____ | Cables _____ | |
| Topsides _____ | Ceiling _____ | Hawsers and Warps _____ | |
| Wales _____ | Rudder _____ | Standing and Running Rigging _____ | |
| Plank (Bottom) and Counter _____ | Copper _____ When put on _____ | | |
| General Observations and Opinion, _____ | | | |
| Caulking of Bottom, Deck, and Waterways _____ | | | |
| Committee's Minute _____ 18____ | | | |
| Character assigned _____ | | | |