

## ANNUAL SURVEYS.

25907  
Rev 22/3/80

No. 3899 Survey held at Sharpness Date, first Survey 18 March 1880 Last Survey 18 March 1880  
 No. in on the B<sup>7</sup> Belle of Arvon Master H. Thomas  
 Reg. Book. 227 Tonnage 823 Built at Sunderland When built 1876 Sms  
923 By whom built Osborne Owners Thomas Griffiths & Co  
 Port belonging to Liverpool Destined Voyage N. C. of America  
 If Surveyed Afloat or in Dry Dock Sharpness Dry Dock

Last Survey, No. 21918 Port of Iron Classified 100A  
 Years assigned. 10.78  
 Character in Register Book.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Breasthooks and Stenson <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Timbers of the Frame at the Openings <u>Good</u>	Pumps <u>Good</u>
Comings <u>Good</u>	Ditto ditto at other places <u>Good</u>	Keelsons <u>Good</u>	Boats <u>3 in No</u>
Upper Deck Beams & Fastenings <u>Good</u>	Clamps and Shelves <u>Good</u>	Ceiling <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Rudder <u>Good</u>	Copper or Y.M. Cement When put on <u>76</u>	Condition, how ascertained <u>From deck</u>
Planksheers <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Standing and Running Rigging <u>Good</u>	Sails <u>Good</u>
Sheerstrakes <u>Good</u>	Engine Room Skylights <u>Good</u>	Coal Bunker, Openings, Lids, &c. <u>Good</u>	Anchors, No. of <u>3 B. 18. 2 K</u>
Topsides <u>Good</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>	Cables <u>part seen</u>
Wales <u>Good</u>	Hatches <u>Good</u>		Haulers and Warps <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>			

General Observations, Opinion as to Class, &c. Vessel surveyed in dry dock with ballast covering about half the length of the hold. Two strakes of shifting hatches in close ceiling lifted before and abaft ballast on both sides and the cement found in good condition. She is now in a good and efficient condition and eligible in my opinion to remain as classed. The Owner desires to defer S.S. not until vessel returns.

Committee's Minute Tuesday, March, 23rd 1880,Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 18

No.                      Survey held at                      Date, first Survey                      Last Survey                       
 No. in on the                      Master                       
 Reg. Book.                      Tonnage                      Built at                      When built                       
 By whom built                      Owners                       
 Port belonging to                      Destined Voyage                       
 If Surveyed Afloat or in Dry Dock                     

Last Survey, No.                      Port of                      Classified                       
 Years assigned.                       
 Character in Register Book.

Present Condition of the

Decks <u>                    </u>	Treenails <u>                    </u>	Breasthooks and Stenson <u>                    </u>	Windlass and Capstan <u>                    </u>
Waterways <u>                    </u>	Transoms, Pointers, and Crutches <u>                    </u>	Timbers of the Frame at the Openings <u>                    </u>	Pumps <u>                    </u>
Comings <u>                    </u>	Ditto ditto at other places <u>                    </u>	Keelsons <u>                    </u>	Boats <u>                    </u>
Upper Deck Beams & Fastenings <u>                    </u>	Clamps and Shelves <u>                    </u>	Ceiling <u>                    </u>	Masts, Yards, &c. <u>                    </u>
Lower Deck Beams & Fastenings <u>                    </u>	Rudder <u>                    </u>	Copper or Y.M. When put on <u>                    </u>	Condition, how ascertained <u>                    </u>
Planksheers <u>                    </u>	Caulking of Bottom, Deck, & Waterways <u>                    </u>	Standing and Running Rigging <u>                    </u>	No. of <u>                    </u>
Sheerstrakes <u>                    </u>	Engine Room Skylights <u>                    </u>	Coal Bunkers, Openings, Lids, &c. <u>                    </u>	Haulers and Warps <u>                    </u>
Topsides <u>                    </u>	Scuppers <u>                    </u>	Cargo and Main Hatchways <u>                    </u>	Hatches <u>                    </u>
Wales <u>                    </u>			
Plank (Bottom) and Counter <u>                    </u>			

General Observations, Opinion as to Class, &c.                     Committee's Minute 18Character assigned                     

Surveyor to Lloyd's Register

Certificate (if required)                     

© 2018  
 Lloyd's Register  
 Foundation