

ANNUAL SURVEYS.

No. 22989 Survey held at London Date, first Survey March 1st Last Survey March 1st 18 80
(Received at London Office, 9. 3. 80)
No. in Reg. Book. 161 on the S S Edinburgh Castle Master Armean
Tonnage 1734 Built at Glasgow When built 1872-3
By whom built Napier Owners S Currie & Co
Port belonging to London Destined Voyage Cape
If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 25201 Port of Iron

Present Condition of the Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Classed	<u>100A1-875</u>	Character in Register Book.	<u>SS Len M176</u>
Waterways	"	Breasthooks and Stemson	"	Windlass and Capstan	<u>Good</u>		
Comings	"	Transoms, Pointers, and Crutches	"	Pumps	"		
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Boats	"		
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Masts, Yards, &c.	"		
Planksheers	"	Keelsons	"	Condition, how ascertained	<u>From Hk</u>		
Sheerstrakes	"	Clamps and Shelves	"	Sails	<u>Good</u>		
Topsides	"	Ceiling	"	Anchors, No. of <u>S Bros. 12 & 1 Ridges</u>			
Wales	"	Rudder	"	Cables <u>Part on Hk</u>	<u>Good</u>		
Plank (Bottom) and Counter	"	<u>Copper or Y.M. Coated</u> When put on <u>new</u>		Hawsers and Warps	"		
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Standing and Running Rigging	"		
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>		
General Observations, Opinion as to Class, &c.	<u>Bottom be coated.</u>						

She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, March, 19th 1880

Character assigned 100A1

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. 22982 Survey held at London Date, first Survey July 24 Last Survey July 26th 18 80
No. in Reg. Book. 317 on the S Airlie Master J. Foreman
Tonnage 1500 Built at Glasgow When built 1875
By whom built Stephens Owners S Bruce & Co
Port belonging to Glasgow Destined Voyage Glasgow
If Surveyed Afloat or in Dry Dock Blackwall Dry Dock & afloat

Last Survey, No. 22982 Port of Iron

Present Condition of the Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Classed	<u>100A1-875</u>	Character in Register Book.	<u>SS Glen M177</u>
Waterways	"	Breasthooks and Stemson	"	Windlass and Capstan	<u>Good</u>		
Comings	"	Transoms, Pointers, and Crutches	"	Pumps	"		
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Boats	"		
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Masts, Yards, &c.	"		
Planksheers	"	Keelsons	"	Condition, how ascertained	<u>From Hk</u>		
Sheerstrakes	"	Clamps and Shelves	"	Sails	<u>Good</u>		
Topsides	"	Ceiling	"	Anchors, No. of <u>S Bros. 12 & 1 Ridges</u>			
Wales	"	Rudder	"	Cables <u>Part on Hk</u>	<u>Good</u>		
Plank (Bottom) and Counter	"	<u>Copper or Y.M. Coated</u> When put on <u>new</u>		Hawsers and Warps	"		
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Standing and Running Rigging	"		
Coal Bunkers, Openings, Lids, &c.		Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>		
General Observations, Opinion as to Class, &c.	<u>Bottom be coated</u>						

She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, March, 19th 1880

Character assigned 100A1

Senhouse Martindale
Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

