

No. 39018 Survey held at London Date, first Survey 11 March Last Survey 12 March 1880

No. in on the S.S. Lord of the Isles Master Felgate  
g. Book. 25973

Tonnage 1584 Built at Glasgow When built 1840-6  
2484

By whom built Napier Owners Thos. P. Bushby &

Port belonging to London Destined Voyage Hamburg

If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 24240 Port of Iron Classed 100 A 7.79  
Years assigned. 5.5.42.78 Character in Register Book.

Present Condition of the	Good	Transoms	Keels
Decks	<u>Good</u>	<u>Keels</u>	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stenson	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>
Deerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>
Oppsides	<u>do</u>	Ceiling	<u>do</u>
Stales	<u>do</u>	Rudder	<u>do</u>
Bottom (Bottom) and Counter	<u>do</u>	Copper or Y.M. When put on	<u>do</u>
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>
Coal Bunkers, Openings, Lids, &c.	<u>do</u>	Windlass and Capstan	<u>do</u>
Scuppers	<u>do</u>	Pumps	<u>do</u>
Cargo and Main Hatchways	<u>do</u>	Boats	<u>do</u>
Hatches	<u>do</u>	Masts, Yards, &c.	<u>do</u>

General Observations, Opinion as to Class, &c.  
Bottom cleaned and recoated. This vessel appears in good condition and eligible to remain as classed.

Committee's Minute Friday, April, 2nd 1880

Character assigned 100 A

J. B. Longdon  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) Paid 18

Laufer  
by  
Lina J. Sales

---



© 2019

Lloyd's Register  
Foundation