

ANNUAL SURVEYS

25975

No. in Reg. Book. on the No. 39009 Survey held at London Date, first Survey March 17 Last Survey March 19 1880
20 Sept Mangerton Master J. Hoys
 Tonnage 1317 Built at Newcastle When built 1879 - 7 mo.
 By whom built Leslie Owners J & Milburn
 Port belonging to London Destined Voyage via Bremen
 If Surveyed Afloat or in Dry Dock James Iron Works by JTC

Last Survey, No. 24523 Port of Iron Classed 100 A. 12.75
Years assigned. Character in Register Book.

Present Condition of the					
Decks	<u>Good</u>	Treenails	<u>Pivets</u>	<u>Good</u>	
Waterways	"	Breasthooks and Stemson		"	
Comings	"	Transoms, Pointers, and Crutches		"	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	
Planksheers	"	Keelsons		"	
Sheerstrakes	"	Clamps and Shelves		"	
Topsides	"	Ceiling		"	
Wales	"	Rudder		"	
Plank (Bottom) and Counter	"	Copper or Y.M. Coated When put on	<u>none</u>	"	
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	"	
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
General Observations, Opinion as to Class, &c.	<u>at present about 16 Rivets in the Keel (Keel) renewed, Bottom &c coated & a few bolts caulked. She is now in good condition and eligible to remain as classed.</u>				

Committee's Minute Thursday, March, 25th 1880
 Character assigned 100 A
 Surveyor Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. in Reg. Book. on the _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Present Condition of the					
Decks		Treenails			
Waterways		Breasthooks and Stemson			
Comings		Transoms, Pointers, and Crutches			
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings			
Lower Deck Beams & Fastenings		Ditto ditto at other places			
Planksheers		Keelsons			
Sheerstrakes		Clamps and Shelves			
Topsides		Ceiling			
Wales		Rudder			
Plank (Bottom) and Counter		Copper or Y.M. When put on			
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways			
Coal Bunkers, Openings, Lids, &c.		Scuppers		Cargo and Main Hatchways	
General Observations, Opinion as to Class, &c.					

Committee's Minute 18
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid 18

