

ANNUAL SURVEYS. 25979

(Received at London Office, 4. 80)

No. 3902 Survey held at London Date, first Survey March 6 Last Survey March 23 18 80
 No. in on the SS Merimethshire Master J. Rickard
 Reg. Book. 979 Tonnage 1245 Built at Glasgow When built 1878-4
 By whom built Sen & Glasb Owners S. J. Jenkins &
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Blackwall Pt by Mr
 Last Survey, No. 24603 Port of Iron Classed 100 A 475


Present Condition of the
 Decks Good Treenails Pine Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Copper When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom & Coated
She is now in good condition and eligible to remain as classed

Committee's Minute Friday, April, 2nd 1880
 Character assigned 100 A 475
Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18 80

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18



SS Mermaid

Character assigned

Committee & Minutes

18

General Observations' Opinion as to Class' &c

Enders Room Register

Costs' Bankers' Observations' Page' &c

Register

Cardo and Main Hierarchy

History

Bank (Bottom) and Counter

Notes

Letters

Specimens

Specimens

Lower Deck Beam & Ribs

Upper Deck Beam & Ribs

Stairs

Materials

Deck

Present Condition of the

Last Survey' No.

Part of

Classed

Surveyed

Specimens in Register Book

A Surveyed Agent or in Day Book

Part referred to

By whom sent

Designated Volume

Owners

Volume

Part of

When sent

Master

Red Book

No. in on the

No.

Surveyed part of

Date' last Surveyed

Last Surveyed

18

Character assigned

Committee & Minutes

18

General Observations' Opinion as to Class' &c

Enders Room Register

Costs' Bankers' Observations' Page' &c

Register

Cardo and Main Hierarchy

History

Bank (Bottom) and Counter

Notes

Letters

Specimens

Specimens

Lower Deck Beam & Ribs

Upper Deck Beam & Ribs

Stairs

Materials

Deck

Present Condition of the

Last Survey' No.

Part of

Classed

Surveyed

Specimens in Register Book

A Surveyed Agent or in Day Book

Part referred to

By whom sent

Designated Volume

Owners

Volume

Part of

When sent

Master

Red Book

No. in on the

No.

Surveyed part of

Date' last Surveyed

Last Surveyed

18

ANNUAL SUBSIDY



© 2019

Lloyd's Register Foundation