

ANNUAL SURVEYS.

26030

No. 38996 Survey held at London Date, first Survey 12th March Last Survey 12th March 1880
 No. in 1 on the S. S. "Zoe" Master H. Doubleday
 Reg. Book. 1 Tonnage 757 1188 966 Built at Newcastle When built 1879 9th mo.
 By whom built Palmer Owners Burdick & Cook
 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 24729 Port of India Classed 100 A1
 Years assigned 9.79 Character in Register Book

Present Condition of the Decks		Treenails		Rivets		Good	
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Windlass and Capstan	<u>Good</u>
Comings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	Ditto ditto at other places	<u>not seen</u>	Pumps	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Keelsons	<u>do</u>	Clamps and Shelves	<u>do</u>	Boats <u>3 in number</u>	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ceiling	<u>do</u>	Rudder	<u>do</u>	Masts, Yards, &c.	<u>do</u>
Planksheers	<u>do</u>	Copper or Y.M. Paint	<u>When put on now</u>	Caulking of Bottom, Deck, & Waterways	<u>good</u>	Condition, how ascertained	<u>from deck & enquiry</u>
Sheerstrakes	<u>do</u>	Bottom, Deck, & Waterways	<u>good</u>	Scuppers	<u>do</u>	Sails	<u>do</u>
Topsides	<u>do</u>	Engine Room Skylights	<u>good</u>	Coal Bunker, Openings, Lids, &c.	<u>good</u>	Anchors, No. of <u>3 B. 1st. 27</u>	<u>do</u>
Wales	<u>do</u>	General Observations, Opinion as to Class, &c.	<u>do</u>		<u>do</u>	Cables <u>part seen</u>	<u>do</u>
Plank (Bottom) and Counter	<u>do</u>					Hawsers and Warps	<u>do</u>
						Standing and Running Rigging	<u>do</u>
						Cargo and Main Hatchways	<u>good</u>
						Hatches	<u>do</u>

Bottom cleaned & repainted.

She is in good condition & eligible in my opinion to remain as classed.

Committee's Minute Thursday, March, 25th 1880
 Character assigned 100 A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 5/ Paid 27.11.1880

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in _____ on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____		Classed _____		Years assigned _____		Character in Register Book _____	
Present Condition of the Decks		Treenails					
Waterways		Breasthooks and Stemson				Windlass and Capstan	
Comings		Transoms, Pointers, and Crutches				Pumps	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings				Boats	
Lower Deck Beams & Fastenings		Ditto ditto at other places				Masts, Yards, &c.	
Planksheers		Keelsons				Condition, how ascertained	
Sheerstrakes		Clamps and Shelves				Sails	
Topsides		Ceiling				Anchors, No. of _____	
Wales		Rudder				Cables	
Plank (Bottom) and Counter		Copper or Y.M. _____ When put on _____				Hawsers and Warps	
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways				Standing and Running Rigging	
Coal Bunkers, Openings, Lids, &c.		Scuppers				Cargo and Main Hatchways	
General Observations, Opinion as to Class, &c.						Hatches	

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____

